





report date: 2024-03-29

General information

Make	HONDA
Model	INSIGHT IMA ES-T
Colour	Black
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-26

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2025-02-02
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #13	2024-01-12 18:42
MOT test number	156590427445
Result	✓ Passed
Next expiry date	2025-02-02
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-01-08 16:46
MOT test number	239823898549
Result	✓ Passed
MOT #11	2022-02-03 16:56
MOT test number	301064337694
Result	✓ Passed
MOT #10	2021-01-21 11:41
MOT test number	509392669654
Result	✓ Passed

Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Fesult

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2019-01-07 10:57

MOT test number 564492646396

Result ✓ Passed

MOT test number

Result

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #6

MOT test number

Result

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT test number

Result

Pass with rectification

Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 4/12



YE59XBT report date: 2024-03-29

MOT #4	2016-01-14 09:42
MOT test number	654983600599

Result ✓ Passed

MOT #3 2015-01-08 11:33 MOT test number 419738005085

Result
✓ Passed

MOT #2 2014-01-09 12:21

MOT test number 536229804067

Result Passed

MOT #1 2013-01-09 12:46

MOT test number 939199903055

CarCheck.co.uk page 5/12



YE59XBT report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	AIR SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-01-20
Last registration	2024-01-12
Complete history	See info



Registration #1	2010-01-20	24 mi
Registration #2	2013-01-09	9.873 mi
Registration #3	2014-01-09	12.837 mi
Registration #4	2015-01-08	15.385 mi
Registration #5	2016-01-14	18.261 mi
Registration #6	2017-01-11	20.404 mi
Registration #7	2017-01-11	20.404 mi
Registration #8	2018-01-10	22.859 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		10.777 es

More info >

CarCheck.co.uk page 11/12



YE59XBT report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 1072437

CarCheck.co.uk page 12/12