



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC 136PS
Colour	Black
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2024-09-14
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	42
Total items failed	27

MOT #16	2023-09-08 09:25
MOT test number	363972714642
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2023-09-07 09:49

MOT test number

372733096604

Result**✗ Failed**

- Fail** Nearside Rear Road wheel has a welding defect (5.2.2 (a))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Stop lamp(s) emits other than a steady red light stop lights (4.3.3 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #14

2022-08-16 15:32

MOT test number

988929019630

Result**✓ Passed**

- Advice** Front registration plate damaged
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside front wing corroded at the bottom
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #13**

2022-08-16 11:17

MOT test number

296446307746

Result

✗ Failed

- Advice** Front registration plate damaged
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside front wing corroded at the bottom
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #12

2021-08-30 16:01

MOT test number

980687198488

Result

✓ Passed

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2020-09-15 11:45**MOT test number** 396305721505**Result** ✓ Passed**Advice** Front Vehicles internal headlight adjuster altered to recheck lights**Advice** Under tray fitted**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2020-09-05 09:37**MOT test number** 852633103373**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Advice** Engine/Tray Covers Fitted restricting inspection**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Exhaust Hangers corroded**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Oil Leak**Fail** Fuel system component leaking From top of engine near fuel lines (6.1.3 (b) (i))**Advice** Various Rear Suspension bushes deteriorated**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #9** 2019-09-05 08:52**MOT test number** 122842631250**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge slight wear inner edge (5.2.3 (e))**MOT #8** 2018-08-13 09:01**MOT test number** 647312613753**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2017-08-14 12:06**MOT test number** 175289193234**Result** ✓ Passed**MOT #6** 2017-08-14 09:08**MOT test number** 586634844404**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #5** 2016-08-17 15:20**MOT test number** 274869603302**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #4 2016-08-17 11:13**MOT test number** 781451376877**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #3 2015-09-07 11:29**MOT test number** 407071996557**Result** ✓ Passed**MOT #2** 2014-09-08 13:39**MOT test number** 809201654276**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)



MOT #1	2013-09-06 16:37
MOT test number	515639843282
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
19 February 2024

✓

MOT

Expires:
14 September 2024

Tax status	Expired at 19 February 2024
Days left	70 days too late
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX60HWG
Plate since	2019-09-29
Current registration	EX60HWG
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-01
Last registration	2023-09-08
Complete history	See info



Registration #1	2010-09-01	11 mi
Registration #2	2013-09-06	33.510 mi
Registration #3	2014-09-08	45.997 mi
Registration #4	2015-09-07	60.402 mi
Registration #5	2016-08-17	71.729 mi
Registration #6	2016-08-17	71.729 mi
Registration #7	2017-08-14	81.645 mi
Registration #8	2017-08-14	81.646 mi
Registration #9	2018-08-13	96.078 mi
Registration #10	2019-08-13	111.010 mi
Registration #11	2019-08-13	111.010 mi
Registration #12	2019-08-13	111.010 mi
Registration #13	2019-08-13	111.010 mi
Registration #14	2019-08-13	111.010 mi
Registration #15	2019-08-13	111.010 mi
Registration #16	2019-08-13	111.010 mi
Registration #17	2019-08-13	111.010 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

AB89987