



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI 2 ECODYNAMICS
Colour	Silver
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	15.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-11
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	16
Total items failed	18

MOT #15	2023-08-11 06:39
MOT test number	781381498418
Result	✓ Passed
Next expiry date	2024-08-11
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14	2023-08-10 10:08
MOT test number	985793825248
Result	✗ Failed
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13	2022-08-03 07:30
MOT test number	271149861854
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-08-12 12:28**MOT test number** 662034761939**Result** ✓ Passed**MOT #11** 2021-08-11 13:18**MOT test number** 439695575225**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #10** 2020-01-10 15:19**MOT test number** 987583124476**Result** ✓ Passed**MOT #9** 2020-01-09 12:00**MOT test number** 309135237694**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #8** 2019-01-12 10:58**MOT test number** 621879811627**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge On 1.6mm (5.2.3 (e))**Advice** Rear Brake pads getting low**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2018-01-11 11:43**MOT test number** 751840723623**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2018-01-09 14:59**MOT test number** 542174686926**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit On limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2017-01-12 10:02**MOT test number** 438704813017**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #4** 2017-01-12 10:02**MOT test number** 609158571743**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm 195/55x16 (4.1.E.1)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #3 2016-01-11 10:45**MOT test number** 228054779864**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2014-12-04 15:38**MOT test number** 819648434331**Result** ✓ Passed**MOT #1** 2014-12-04 10:09**MOT test number** 917288834367**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Pass with rectification** Nearside Front Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
11 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	11 August 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-30
Last registration	2023-08-11
Complete history	See info



Registration #1	2011-12-30	24 mi
Registration #2	2014-12-04	33.999 mi
Registration #3	2014-12-04	33.999 mi
Registration #4	2016-01-11	44.488 mi
Registration #5	2017-01-12	58.685 mi
Registration #6	2017-01-12	58.685 mi
Registration #7	2018-01-09	71.200 mi
Registration #8	2018-01-11	71.200 mi
Registration #9	2019-01-12	79.167 mi
Registration #10	2019-01-12	79.167 mi
Registration #11	2019-01-12	79.167 mi
Registration #12	2019-01-12	79.167 mi
Registration #13	2019-01-12	79.167 mi
Registration #14	2019-01-12	79.167 mi
Registration #15	2019-01-12	79.167 mi
Registration #16	2019-01-12	79.167 mi
Registration #17	2019-01-12	79.167 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1293 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D3FABH300246