



**SEI2FPF**

report date: 2024-03-29

General information

Make	KIA
Model	RIO 1 AIR
Colour	Silver
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-06
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-16
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	42
Total items failed	8

MOT #13	2023-07-17 15:32
MOT test number	376826285883
Result	✓ Passed
Next expiry date	2024-07-16
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #12** 2023-07-17 15:32**MOT test number** 642889883895**Result** ✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #11** 2022-07-12 14:37**MOT test number** 566316376768**Result** ✓ Passed

- Advice** Suspension component corroded but not seriously weakened Front and Rear Suspension covered with under seal (5.3.3 (b) (i))

**MOT #10** 2020-10-13 16:05**MOT test number** 185859856780**Result** ✓ Passed

- Advice** Front Subframe mounting repair covered in underseal and rear both (5.3.6 (a) (i))

**MOT #9** 2020-08-29 08:25**MOT test number** 838790654554**Result** ✗ Failed**Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Exhaust mounting defective in front of rear box (6.1.2 (a))**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside front suspension arm rear bush starting to split**MOT #8** 2019-08-24 09:40**MOT test number** 992964918908**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-08-24 09:07**MOT test number** 865338090590**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-08-27 08:56**MOT test number** 326338140486**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



**MOT #5**

2017-08-28 08:57

**MOT test number**

998036309162

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit 3mm - 18565R15 88H (4.1.E.1)
- Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened worn, signs of overheating & lightly scored (3.5.1i)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit 3MM - 185/65R15 88H (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn & "lipped" (3.5.1i)

**MOT #4**

2017-08-28 08:25

**MOT test number**

557180095004

**Result**

✗ Failed

- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Tyre worn close to the legal limit 3mm - 18565R15 88H (4.1.E.1)
- Advice** Nearside Rear Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened worn, signs of overheating & lightly scored (3.5.1i)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Front Tyre worn close to the legal limit 3MM - 185/65R15 88H (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn & "lipped" (3.5.1i)

**MOT #3** 2016-08-13 08:10**MOT test number** 156392925569**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #2** 2015-08-19 10:17**MOT test number** 356131935268**Result** ✓ Passed**Notice** Offside rear tyre tread cracked & perished**MOT #1** 2015-08-19 09:22**MOT test number** 635041235269**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Offside rear tyre tread cracked & perished**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
16 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	16 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

SE12FPF	2019-01-01
SE12FPF	2019-01-01
SE12FPF	2019-01-01
SE12FPF	2019-01-01
SE12FPF	2019-01-01
SE12FPF	2019-01-01
SE12FPF	2019-01-01

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SE12FPF
Plate since	2019-01-01
Current registration	SE12FPF
Plate since	2019-01-01

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-08-24
Last registration	2023-07-17
Complete history	<a href="#">See info</a>



Registration #1	2012-08-24	27 mi
Registration #2	2015-08-19	43.200 mi
Registration #3	2015-08-19	43.201 mi
Registration #4	2016-08-13	58.204 mi
Registration #5	2017-08-28	66.743 mi
Registration #6	2017-08-28	66.743 mi
Registration #7	2018-08-27	71.446 mi
Registration #8	2019-08-24	77.345 mi
Registration #9	2020-08-20	83.244 mi
Registration #10	2021-08-17	89.143 mi
Registration #11	2022-08-14	95.042 mi
Registration #12	2023-07-17	100.941 mi
Registration #13	2023-07-17	100.941 mi
Registration #14	2023-07-17	100.941 mi
Registration #15	2023-07-17	100.941 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1211 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4LACP092937