



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA ELITE 16V
Colour	Black
Year of manufacture	2007
Top speed	129 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	155 BHP
Max. torque	265 Nm at 2.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.3 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.1 mpg
CO2 emission	197 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-21
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-20
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	20
Total items failed	4

MOT #21	2023-08-03 07:01
MOT test number	491167663979
Result	✓ Passed
Next expiry date	2024-08-20
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20	2023-08-01 08:15
MOT test number	448871988869
Result	✗ Failed
MAJOR	Front Exhaust system insecure (6.1.2 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Central Exhaust system insecure (6.1.2 (a))

MOT #19	2022-07-26 15:57
MOT test number	504065054898
Result	✓ Passed
Advice	Front Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #18** 2022-07-26 11:06**MOT test number** 893339989416**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Exhaust mounting defective (6.1.2 (a))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #17** 2021-08-21 15:40**MOT test number** 751864484935**Result** ✓ Passed**MOT #16** 2020-11-07 13:27**MOT test number** 634626217955**Result** ✓ Passed**MOT #15** 2020-11-07 13:27**MOT test number** 247929969429**Result** ✗ Failed**Pass with rectification** Rear Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))**MOT #14** 2019-11-15 10:10**MOT test number** 359906331711**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))



MOT #13	2019-11-14 12:32
MOT test number	827159146070
Result	✗ Failed
MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
DANGEROUS Rear Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))	
MAJOR Front Exhaust system insecure (6.1.2 (a))	
MAJOR Brake pipe excessively damaged main (both) (1.1.11 (c))	
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #12	2018-11-13 09:26
MOT test number	440897027081
Result	✓ Passed

MOT #11	2017-11-15 17:18
MOT test number	248583386742
Result	✓ Passed

MOT #10	2017-11-15 15:10
MOT test number	963958646130
Result	✗ Failed
Fail	Nearside Rear coil spring broken (2.4.C.1a)

MOT #9	2016-11-08 09:12
MOT test number	321030343065
Result	✓ Passed

MOT #8	2015-11-16 16:55
MOT test number	451086875259
Result	✓ Passed

**MOT #7** 2015-11-16 12:25**MOT test number** 603048173314**Result** ✗ Failed**Fail** Offside Rear coil spring fractured (2.4.C.1a)**MOT #6** 2014-10-03 09:43**MOT test number** 948086874266**Result** ✓ Passed**MOT #5** 2013-09-23 11:32**MOT test number** 148306563204**Result** ✓ Passed**MOT #4** 2012-09-19 10:54**MOT test number** 147003062203**Result** ✓ Passed**MOT #3** 2011-09-22 17:28**MOT test number** 477945361271**Result** ✓ Passed**MOT #2** 2010-09-15 11:41**MOT test number** 391498750284**Result** ✓ Passed**MOT #1** 2010-09-15 11:41**MOT test number** 373808750265**Result** ✗ Failed**Pass with rectification** Steering system has excessive free play detected at the steering wheel (steering rack fitted) (2.2.A.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 August 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 NL57NBE
Plate since	2019-06-29
Current registration	 NL57NBE
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-30
Last registration	2023-08-03
Complete history	See info



Registration #1	2007-09-30	13 mi
Registration #2	2010-09-15	18.135 mi
Registration #3	2011-09-22	19.661 mi
Registration #4	2012-09-19	21.348 mi
Registration #5	2013-09-23	22.902 mi
Registration #6	2014-10-03	24.285 mi
Registration #7	2015-11-16	25.564 mi
Registration #8	2015-11-16	25.564 mi
Registration #9	2016-11-08	26.698 mi
Registration #10	2017-11-15	35.155 mi
Registration #11	2017-11-15	35.155 mi
Registration #12	2018-05-29	35.155 mi
Registration #13	2018-05-29	35.155 mi
Registration #14	2018-05-29	35.155 mi
Registration #15	2018-05-29	35.155 mi
Registration #16	2018-05-29	35.155 mi
Registration #17	2018-05-29	35.155 mi
Registration #18	2018-05-29	35.155 mi
Registration #19	2018-05-29	35.155 mi
Registration #20	2018-05-29	35.155 mi
Registration #21	2018-05-29	35.155 mi
Registration #22	2018-05-29	35.155 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1509 kg
Max. allowed weight	2115 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	11674271