



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT T200 L SWB P/V
Colour	Blue
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-16
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-29
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	75
Total items failed	41

MOT #26	2023-11-27 11:05
---------	------------------

MOT test number	147480823968
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-11-29
------------------	------------

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Seat belt anchorage prescribed area is corroded but not considered excessive n/s & o/s inner & outer sills (7.1.1 (a) (i))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Headlamp has a product on the lens but not seriously reducing light output n/s & o/s (4.1.4 (b))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive n/s & o/s outer sills (5.3.6 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #25**

2023-11-25 09:50

MOT test number

231962338494

Result**✗ Failed**

- Advice** Headlamp has a product on the lens but not seriously reducing light output n/s & o/s (4.1.4 (b))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive n/s & o/s outer sills (5.3.6 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Seat belt anchorage prescribed area is corroded but not considered excessive n/s & o/s inner & outer sills (7.1.1 (a) (i))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #24

2022-11-30 16:40

MOT test number

449449909897

Result**✓ Passed**

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive centre outer floor to sill (7.1.1 (a) (i))

**MOT #23** 2022-11-28 15:50**MOT test number** 920821402365**Result** ✗ Failed

- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive centre outer floor to sill (7.1.1 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Rear Brake pipe excessively corroded n/s & o/s (1.1.11 (c))

MOT #22 2021-11-24 17:12**MOT test number** 299300700075**Result** ✓ Passed

- Advice** Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush rear (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2021-11-23 12:39

MOT test number

400302353295

Result**✗ Failed**

- Fail** Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Direction indicator slightly discoloured both sides (4.4.3 (a))
- Minor** Headlamp lens slightly defective both sides (4.1.1 (b) (ii))
- Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Advice** Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush rear (5.3.4 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #20

2020-11-24 17:35

MOT test number

969494330100

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2020-11-23 16:29

MOT test number

528276248105

Result

✗ Failed

- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Front Fuel pipe leaking from filter (6.1.3 (b) (i))
- Fail** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Fail** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18

2019-05-16 09:18

MOT test number

566658153511

Result

✓ Passed

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17

2018-05-16 16:17

MOT test number

269342528009

Result

✓ Passed

**MOT #16**

2017-05-24 16:14

MOT test number

531621967682

Result

✓ Passed

- Advice** Windscreen cracked nearside
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #15

2017-05-24 08:58

MOT test number

788049856155

Result

✗ Failed

- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Headlamp aim too low (1.8)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Windscreen cracked nearside
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim too low (1.8)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)

**MOT #14** 2016-04-22 15:23**MOT test number** 471683795745**Result** ✓ Passed**MOT #13** 2016-04-22 09:44**MOT test number** 606341503402**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Battery insecure (1.9.1)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)**MOT #12** 2015-05-07 14:49**MOT test number** 297887925449**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**MOT #11** 2015-05-07 09:46**MOT test number** 359157625188**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #10** 2014-05-15 14:34**MOT test number** 635725634140**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-05-21 16:00**MOT test number** 888761843133**Result** ✓ Passed**MOT #8** 2013-05-20 12:34**MOT test number** 605600243163**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #7** 2012-05-15 16:27**MOT test number** 836096032173**Result** ✓ Passed**Advice** Offside rear brake juddering slightly (3.7.A.5b)**Notice** Battery insecure**Advice** Nearside rear brake juddering slightly (3.7.A.5b)

**MOT #6**

2012-05-15 15:25

MOT test number

687576932106

Result**✗ Failed****Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside rear brake juddering slightly (3.7.A.5b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside rear brake juddering slightly (3.7.A.5b)**Notice** Battery insecure**MOT #5**

2011-05-17 12:50

MOT test number

836047031178

Result**✓ Passed****Notice** Spare tyre defective**Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #4** 2011-05-17 12:50**MOT test number** 447987331109**Result** ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)
- Pass with rectification** Offside Headlamp not working on main beam (1.7.5a)
- Notice** Spare tyre defective
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification** Front brake application uneven (3.7.B.2)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

MOT #3 2010-05-19 15:12**MOT test number** 252399330448**Result** ✓ Passed**MOT #2** 2009-05-12 16:57**MOT test number** 903512339173**Result** ✓ Passed



MOT #1	2009-05-12 09:14
MOT test number	654872739133
Result	✗ Failed
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Stop lamp not working (1.2.1b)
Advice	Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✗
Untaxed

Tax expired:
26 March 2024

✓
MOT

Expires:
29 November 2024

Tax status

Expired at 26 March 2024

Days left

33 days too late

MOT expiry date

29 November 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2006-06-14
Last registration	2023-11-27
Complete history	See info



Registration #1	2006-06-14	6 mi
Registration #2	2009-05-12	36.642 mi
Registration #3	2009-05-12	36.642 mi
Registration #4	2010-05-19	58.292 mi
Registration #5	2011-05-17	72.735 mi
Registration #6	2012-05-15	84.342 mi
Registration #7	2012-05-15	84.342 mi
Registration #8	2013-05-20	89.893 mi
Registration #9	2013-05-21	89.893 mi
Registration #10	2014-05-15	100.050 mi
Registration #11	2015-05-07	111.963 mi
Registration #12	2015-05-07	111.963 mi
Registration #13	2016-04-22	121.925 mi
Registration #14	2016-04-22	121.925 mi
Registration #15	2016-05-20	121.925 mi
Registration #16	2016-05-20	121.925 mi
Registration #17	2016-05-20	121.925 mi
Registration #18	2016-05-20	121.925 mi
Registration #19	2016-05-20	121.925 mi
Registration #20	2016-05-20	121.925 mi
Registration #21	2016-05-20	121.925 mi
Registration #22	2016-05-20	121.925 mi
Registration #23	2016-05-20	121.925 mi
Registration #24	2016-05-20	121.925 mi
Registration #25	2016-05-20	121.925 mi
Registration #26	2016-05-20	121.925 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1410 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	6Y16583