



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 TDI P/V
Colour	Grey
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.9 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-22
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	28
Total items failed	0

MOT #10	2023-10-23 08:00
MOT test number	319995773775
Result	✓ Passed
Next expiry date	2024-10-22

MOT #9	2022-10-22 08:23
MOT test number	674723491678
Result	✓ Passed

MOT #8	2021-10-19 15:17
MOT test number	521005859483
Result	✓ Passed

MOT #7	2020-10-16 08:22
MOT test number	113444094947
Result	✓ Passed

- Advice** Nearside Rear bumper is damaged
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Nearside Front Outer cv boot is slightly deteriorated

**MOT #6**

2019-08-17 07:45

MOT test number

816550315794

Result

✓ Passed

- Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** N/s/r bumper slightly damaged
- Advice** Offside Oil leak, but not excessive Driveshaft seal (8.4.1 (a) (i))

MOT #5

2018-08-22 09:19

MOT test number

294164154046

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Both rear tyre valves slightly damaged
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Coolant leak
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #4

2017-01-10 11:52

MOT test number

443463106229

Result

✓ Passed

- Advice** No emissions detected at time of test

**MOT #3** 2016-01-11 09:42**MOT test number** 688777613469**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-01-08 10:04**MOT test number** 296488905063**Result** ✓ Passed**Notice** Offside door mirror damaged**Notice** Engine oil level low**MOT #1** 2014-01-07 09:19**MOT test number** 418107004049**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)**Notice** Near side rear tyre cut to cords but not exceeding requirements



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 March
-------------------	---------------------

Days left	305
------------------	-----

MOT expiry date	22 October 2024
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GY60YZP
Plate since	2019-06-29
Current registration	 GY60YZP
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-01-11
Last registration	2023-10-23
Complete history	See info



Registration #1	2011-01-11	13 mi
Registration #2	2014-01-07	85.760 mi
Registration #3	2015-01-08	122.304 mi
Registration #4	2016-01-11	147.567 mi
Registration #5	2017-01-10	165.606 mi
Registration #6	2018-08-22	166.136 mi
Registration #7	2019-05-29	167.277 mi
Registration #8	2020-05-29	167.277 mi
Registration #9	2021-05-29	167.277 mi
Registration #10	2022-05-29	167.277 mi
Registration #11	2023-05-29	167.277 mi
Registration #12	2024-05-29	167.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2283 mm
Height	2476 mm
Length	5292 mm
Kerb weight	1912 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	CAA 197076