



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF INDIVIDUAL TDI
Colour	Blue
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	<a href="#">View report</a>

source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-17
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #15	2024-03-01 14:43
MOT test number	598849786385
Result	✓ Passed
Next expiry date	2025-03-17
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened O/S and N/S (1.1.14 (a) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened O/S and N/S (1.1.14 (a) (ii))

MOT #14	2023-02-27 15:53
MOT test number	198674258916
Result	✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

**MOT #13**

2023-02-24 09:58

**MOT test number**

882615048433

**Result**

✗ Failed

**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12**

2022-02-24 09:33

**MOT test number**

203880618541

**Result**

✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Undertrays fitted at time off test**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear subframe becoming corroded**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11**

2021-03-18 11:34

**MOT test number**

812478552127

**Result**

✓ Passed

**MOT #10**

2020-11-30 15:00

**MOT test number**

165424676014

**Result**

✓ Passed

**MOT #9** 2020-11-25 12:17**MOT test number** 113257798544**Result** ✗ Failed**Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2019-05-02 06:51**MOT test number** 985198898591**Result** ✓ Passed**MOT #7** 2018-04-26 11:12**MOT test number** 824031821184**Result** ✓ Passed**MOT #6** 2017-04-27 06:54**MOT test number** 707225431210**Result** ✓ Passed**MOT #5** 2016-04-28 07:15**MOT test number** 842297405801**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-05-01 09:52**MOT test number** 369191925146**Result** ✓ Passed



MOT #3	2014-04-11 15:25
MOT test number	876171104126
Result	✓ Passed
MOT #2	2013-04-10 10:58
MOT test number	788670003159
Result	✓ Passed
MOT #1	2013-04-10 10:58
MOT test number	218190303414
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
17 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	17 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>BK10LGN</b>
Plate since	2024-03-28
Current registration	<b>BK10LGN</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-28
Last registration	2024-03-01
Complete history	<a href="#">See info</a>



Registration #1	2010-04-28	15 mi
Registration #2	2013-04-10	17.856 mi
Registration #3	2014-04-11	23.903 mi
Registration #4	2015-05-01	32.931 mi
Registration #5	2016-04-28	53.611 mi
Registration #6	2017-04-27	73.815 mi
Registration #7	2018-04-26	93.053 mi
Registration #8	2019-05-02	110.708 mi
Registration #9	2020-05-02	128.363 mi
Registration #10	2021-05-02	146.018 mi
Registration #11	2022-05-02	163.673 mi
Registration #12	2023-05-02	181.328 mi
Registration #13	2024-03-01	198.983 mi
Registration #14	2024-03-01	198.983 mi
Registration #15	2024-03-01	198.983 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1552 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBA 700743