



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA TDI (90BHP)
Colour	Black
Year of manufacture	2007
Top speed	114 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-21
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	34
Total items failed	8

MOT #20	2023-08-29 10:18
MOT test number	439235283986
Result	✓ Passed
Next expiry date	2024-08-31

MOT #19	2022-09-01 12:13
MOT test number	436034043089
Result	✓ Passed

- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Front play to both upper strut mounts
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge both 205/55/16 v (5.2.3 (e))
- Advice** Nearside Rear Inner Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Advice** Rear exhaust silencer heavily corroded
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Offside Front Nail in tyre

**MOT #18**

2022-08-26 12:09

MOT test number

302594167063

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge both 205/55/16 v (5.2.3 (e))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Front play to both upper strut mounts
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Nail in tyre
- Fail** Offside Rear Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Rear exhaust silencer heavily corroded
- Fail** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Advice** Nearside Rear Inner Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))

MOT #17

2021-08-26 11:07

MOT test number

421292123367

Result**✓ Passed****MOT #16**

2021-08-25 14:40

MOT test number

998995897120

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2020-11-24 12:33**MOT test number** 385234002692**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn low on shoulders (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking in treads (5.2.3 (d) (ii))**MOT #14** 2019-11-25 16:14**MOT test number** 943171197840**Result** ✓ Passed**MOT #13** 2019-11-25 15:06**MOT test number** 771959519931**Result** ✗ Failed**Fail** Offside Rear Rear fog lamp adversely affected by the operation of another lamp (4.5.4 (b))**MOT #12** 2019-08-19 10:32**MOT test number** 396704047864**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2018-08-22 08:24**MOT test number** 492358852891**Result** ✓ Passed**MOT #10** 2017-09-04 11:33**MOT test number** 697348681134**Result** ✓ Passed**Advice** Offside Front Brake hose slightly damaged (3.6.B.4d)

**MOT #9** 2016-09-09 10:54**MOT test number** 425527237247**Result** ✓ Passed**Advice** Exhaust system corroded**MOT #8** 2016-09-08 11:27**MOT test number** 318784838268**Result** ✗ Failed**Advice** Brake discs corroded/worn**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Advice** Exhaust system corroded**MOT #7** 2015-08-26 13:35**MOT test number** 297498735279**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-08-22 14:51**MOT test number** 168834134293**Result** ✓ Passed**Notice** Inner edge of nearside front tyre worn.

**MOT #5** 2013-08-14 09:14**MOT test number** 997076123233**Result** ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice O/s/r parking brake not going back to stop

MOT #4 2013-08-14 09:14**MOT test number** 165166923252**Result** ✗ Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice O/s/r parking brake not going back to stop

MOT #3 2012-08-15 09:14**MOT test number** 115258822226**Result** ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2011-08-26 09:38**MOT test number** 877198231246**Result** ✓ Passed**MOT #1** 2010-08-26 11:35**MOT test number** 554238630268**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KU57CXY
Plate since	2024-03-29
Current registration	 KU57CXY
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-01
Last registration	2023-08-29
Complete history	See info



Registration #1	2007-09-01	27 mi
Registration #2	2010-08-26	6.931 mi
Registration #3	2011-08-26	11.460 mi
Registration #4	2012-08-15	19.065 mi
Registration #5	2013-08-14	29.457 mi
Registration #6	2014-08-22	40.744 mi
Registration #7	2015-08-26	42.829 mi
Registration #8	2016-09-08	46.245 mi
Registration #9	2016-09-09	46.246 mi
Registration #10	2017-09-04	54.149 mi
Registration #11	2018-08-22	58.985 mi
Registration #12	2019-08-22	63.821 mi
Registration #13	2020-08-22	68.657 mi
Registration #14	2021-08-22	73.493 mi
Registration #15	2022-08-22	78.329 mi
Registration #16	2023-08-22	83.165 mi
Registration #17	2024-08-22	88.001 mi
Registration #18	2025-08-22	92.837 mi
Registration #19	2026-08-22	97.673 mi
Registration #20	2027-08-22	102.509 mi
Registration #21	2028-08-22	107.345 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1580 mm
Length	4206 mm
Wheel base	2578 mm
Kerb weight	1572 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE 343433