



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Silver
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-15
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #14	2021-10-06 15:46
MOT test number	305305083223
Result	✓ Passed
Next expiry date	2022-10-13
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Perishing / cracking (5.2.3 (d) (ii))

MOT #13	2021-10-06 15:46
MOT test number	671322940549
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Perishing / cracking (5.2.3 (d) (ii))

MOT #12	2020-10-09 15:03
MOT test number	161464753052
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11	2020-10-08 16:22
MOT test number	287317806219
Result	✗ Failed
Fail	Nearside Rear Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Rear Exhaust system insecure (6.1.2 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2019-10-14 10:19
MOT test number	432059386163
Result	✓ Passed
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #9** 2018-10-12 10:15**MOT test number** 958747380906**Result** ✓ Passed**MOT #8** 2018-10-10 14:33**MOT test number** 861413360552**Result** ✗ Failed**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**MOT #7** 2017-10-10 10:01**MOT test number** 929660126483**Result** ✓ Passed**MOT #6** 2016-10-03 10:48**MOT test number** 999401389268**Result** ✓ Passed**MOT #5** 2015-10-07 14:18**MOT test number** 494986907417**Result** ✓ Passed**MOT #4** 2015-10-06 14:55**MOT test number** 417083391406**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed sidewall (4.1.D.1b)**Fail** Nearside Front Brake hose excessively damaged (3.6.B.4d)



MOT #3	2014-10-14 16:19
MOT test number	718447284216
Result	✓ Passed
Notice	Nail in n/s/r tyre
Notice	O/s/r tyre worn on inner edge

MOT #2	2013-09-10 15:53
MOT test number	157743353264
Result	✓ Passed

MOT #1	2012-09-10 14:58
MOT test number	337604452202
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-04
Last registration	2021-10-06
Complete history	See info



Registration #1	2009-09-04	13 mi
Registration #2	2012-09-10	61.147 mi
Registration #3	2013-09-10	66.278 mi
Registration #4	2014-10-14	71.392 mi
Registration #5	2015-10-06	77.133 mi
Registration #6	2015-10-07	77.134 mi
Registration #7	2016-10-03	82.336 mi
Registration #8	2017-10-10	86.834 mi
Registration #9	2018-10-10	91.332 mi
Registration #10	2019-10-10	95.830 mi
Registration #11	2020-10-10	100.328 mi
Registration #12	2021-10-10	104.826 mi
Registration #13	2022-10-10	109.324 mi
Registration #14	2023-10-10	113.822 mi
Registration #15	2024-10-10	118.320 mi
Registration #16	2025-10-10	122.818 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9B03425