





report date: 2024-03-29

General information

Make	LAND ROVER
Model	DISCOVERY SPORT TD4 SE TECH
Colour	White
Year of manufacture	2018
Top speed	117 mph
0 - 100 km/h	8.9 seconds
0 - 60 mph	8.9 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	132 kW / 180 HP / 178 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.9 mpg
Consumption extra urban	40.6 mpg
Consumption combined	2.8 mpg
CO2 emission	170 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



RE68VYY

report date: 2024-03-29

Internet history


Entry 3

Date 2022-05-25

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk

Entry 2


27
2

Pictures 25

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2022-04-24


Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



RE68VYY

report date: 2024-03-29

MOT history

MOT expiry date	2024-07-12
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #5	2023-07-13 11:57
MOT test number	128513846220
Result	✓ Passed
Next expiry date	2024-07-12

MOT #4	2022-07-01 11:37
MOT test number	899369251554
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2022-06-30 14:35
MOT test number	505128621787
Result	× Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Rear Brake disc significantly and obviously worn both (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



RE68VYY

report date: 2024-03-29

MOT test number

455012229653

Result

Minor

Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2021-11-25 15:20 **MOT** test number 910169113544 Result × Failed Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i)) Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-11-29
Last registration	2023-07-13
Complete history	See info



Registration #1	2018-11-29	13 mi
Registration #2	2021-11-25	21.691 mi
Registration #3	2021-11-26	21.691 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	93%
Children	83%
Pedestrian	69%
Safety systems	82%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1894 mm
Height	1724 mm
Length	4589 mm
Wheel base	2741 mm
Kerb weight	1780 kg
Max. allowed weight	2660 kg

Additional information

Fuel tank capacity	54 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	180918W0471204DTD

CarCheck.co.uk page 11/11