



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Black
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-25
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	39
Total items failed	5

MOT #17	2024-03-02 09:37
MOT test number	842001632891
Result	✓ Passed
Next expiry date	2025-03-25
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-03-15 12:06
MOT test number	496962547183
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))

**MOT #15** 2023-03-03 15:32**MOT test number** 296826598287**Result** ✗ Failed

**MAJOR** Nearside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MAJOR** Offside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))

**MAJOR** Windscreen washer not working (3.5 (a))

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #14** 2022-03-17 17:13**MOT test number** 502479517758**Result** ✓ Passed**MOT #13** 2022-03-11 10:33**MOT test number** 424289574575**Result** ✗ Failed

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2021-03-26 12:50**MOT test number** 606907089267**Result** ✓ Passed



## MOT #11

2021-03-25 11:05

## MOT test number

682773205127

## Result

✗ Failed

- MAJOR** Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

## MOT #10

2019-11-28 14:30

## MOT test number

340730268270

## Result

✓ Passed

- Advice** Nearside Front Coil spring worn (5.3.1 (b) (i))
- Advice** Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Upper Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))

## MOT #9

2018-06-07 11:29

## MOT test number

613591455252

## Result

✓ Passed

## MOT #8

2018-06-06 14:04

## MOT test number

691242440138

## Result

✗ Failed

- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))



<b>MOT #7</b>	2017-05-27 10:17
<b>MOT test number</b>	355011904022
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak

<b>MOT #6</b>	2017-05-27 10:17
<b>MOT test number</b>	824327515159
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
<b>Pass with rectification</b>	Fuel cap/sealing device missing (7.2.4a)
<b>Pass with rectification</b>	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
<b>Advice</b>	Oil leak

<b>MOT #5</b>	2015-12-22 12:02
<b>MOT test number</b>	261448146424
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front running lamp inop
<b>Advice</b>	Nearside Rear side wall of tyre damaged
<b>Advice</b>	Oil leak suspect engine

<b>MOT #4</b>	2014-12-24 09:45
<b>MOT test number</b>	388498054335
<b>Result</b>	✓ Passed
<b>Notice</b>	Nearside front and nearside rear tyre outer side walls of tyres damaged

**MOT #3** 2014-12-24 09:45**MOT test number** 689698954347**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Nearside front and nearside rear tyre outer side walls of tyres damaged**MOT #2** 2013-12-31 13:26**MOT test number** 446745463373**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre outer side wall damaged**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-12-31 13:26**MOT test number** 117865263373**Result** ✗ Failed**Notice** Offside front tyre outer side wall damaged**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
25 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	25 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-15
Last registration	2024-03-02
Complete history	<a href="#">See info</a>



Registration #1	2010-06-15	29 mi
Registration #2	2013-12-31	39.100 mi
Registration #3	2014-12-24	53.005 mi
Registration #4	2015-12-22	63.083 mi
Registration #5	2017-05-27	69.650 mi
Registration #6	2017-05-27	69.650 mi
Registration #7	2018-06-06	75.588 mi
Registration #8	2018-06-07	75.613 mi
Registration #9	2019-11-28	81.682 mi
Registration #10	2020-05-20	85.277 mi
Registration #11	2020-05-20	85.277 mi
Registration #12	2020-05-20	85.277 mi
Registration #13	2020-05-20	85.277 mi
Registration #14	2020-05-20	85.277 mi
Registration #15	2020-05-20	85.277 mi
Registration #16	2020-05-20	85.277 mi
Registration #17	2020-05-20	85.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

**Engine number**

FJBD0799390