





### General information

Make	HONDA
Model	ACCORD CTDI SPORT
Colour	Black
Year of manufacture	2008
Top speed	132 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	148 g/km
CO2 label	F







### Internet history

Entry 2	
Date	2022-07-21
Pictures	28
Listing price	View report



source: cargurus.co.uk

### Entry 1

Date

Pictures

Listing price

2021-06-24 39

View report



source: autotrader.co.uk









## MOT history

MOT expiry date	2024-06-03
MOT pass rate	100 %
MOT passed	13
Failed MOT tests	0
Total advice items	19
Total items failed	0

MOT #13	2023-06-01 12:47
MOT test number	260293018331
Result	✓ Passed
Next expiry date	
Advice Oil leak	
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a)	(i))

MOT #12		2022-06-04 14:37
MOT test	number	931156600913
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice (ii))	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened o	corroded (1.1.14 (a)

MOT #11	2021-05-06 09:30
MOT test number	170969165413
Result	✓ Passed





MOT #10		2020-06-02 10:00
MOT test	number	453323990288
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #9		2019-04-26 08:58
MOT test	number	685340346133
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2018-04-24 15:19
MOT test number	340995210533
Result	✓ Passed
<b>Advice</b> Front Brakes imbalanced requirements only just met. It would requires adjustment or repair. (3.7.B.5b)	d appear that the braking system

MOT #7	2017-04-13 11:33
MOT test number	524346934978
Result	✓ Passed

MOT #6	20	016-04-14 12:01
MOT test	number	855679061056
Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1	)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	





MOT #5	2015-04-21 11:48
MOT test number	706321315167
Result	✓ Passed
MOT #4	2014-04-30 14:41
MOT test number	889060724145
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice O/s/f fog light damaged	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3		2013-05-02 10:10
MOT test	number	406182423156
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2012-05-03 16:26
MOT test number	277944822144
Result	✓ Passed

МОТ #1	2011-08-05 12:14
MOT test number	327167011466
Result	✓ Passed



Tax & MOT check

✓ Taxed	мот
Tax due: 1 July 2024	Expires: 3 June 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	3 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lawer
Туре	(*******	
Damage 2		AMPLE
Damage 2		E CONTRACTOR
Date		
Category		AMP
Туре		

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
*************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this HONDA had different number pla	tes.
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 



RV58XUS report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-01
Last registration	2023-06-01
Complete history	See info



Registration #1	2008-09-01	15 mi
Registration #2	2011-08-05	33.446 mi
Registration #3	2012-05-03	42.403 mi
Registration #4	2013-05-02	50.085 mi
Registration #5	2014-04-30	57.731 mi
Registration #6	2015-04-21	65.172 mi
Registration #7	2016-04-14	72.537 mi
Registration #8	2017-04-13	79.081 mi
Registration #9		10.200 est
Registration #10		11.777 est
-		11.577 es
Registration #10		11.227 46 21.227 46 11.227 46
Registration #10 Registration #11		11.227 est 11.227 est 11.227 est 11.227 est
Registration #10 Registration #11 Registration #12		11.227 46 21.227 46 21.227 46 21.227 46 21.227 46
Registration #10 Registration #11 Registration #12 Registration #13		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >



RV58XUS report date: 2024-03-29

Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1477 kg
Additional information	
Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22A15008470