



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA EDGE
Colour	White
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-06
Pictures	29
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-03-28
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	10
Total items failed	8

MOT #16 2024-03-19 15:59

MOT test number 941845665464

Result ✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #15 2023-03-29 13:04

MOT test number 283023326049

Result ✓ Passed

**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14 2021-06-23 07:58

MOT test number 109860875035

Result ✓ Passed

**MOT #13** 2021-06-23 07:58**MOT test number** 127343956884**Result** ✗ Failed

**Pass with rectification** Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))

**Pass with rectification** Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))

**MOT #12** 2020-07-17 11:21**MOT test number** 348920504197**Result** ✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11** 2019-09-25 12:07**MOT test number** 902061514576**Result** ✓ Passed**MOT #10** 2019-05-29 15:21**MOT test number** 604347169871**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-05-29 13:28**MOT test number** 577512722839**Result** ✗ Failed

**Fail** Offside Front Valve stem seriously damaged (5.2.3 (j))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Valve stem seriously damaged (5.2.3 (j))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-05-25 08:22**MOT test number** 988786382335**Result** ✓ Passed**MOT #7** 2017-06-08 12:40**MOT test number** 872195712572**Result** ✓ Passed**MOT #6** 2017-06-07 11:35**MOT test number** 576085196490**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2016-05-23 14:57**MOT test number** 904235987061**Result** ✓ Passed**MOT #4** 2016-05-23 09:41**MOT test number** 249739228240**Result** ✗ Failed**Fail** Wheel nut(s) missing 3 (4.2.A.1e)**Advice** Nearside Rear light cracks outer wall ?**Advice** Offside Rear light cracks outer wall ?**MOT #3** 2015-05-05 13:09**MOT test number** 216475925470**Result** ✓ Passed



MOT #2	2014-05-06 10:01
MOT test number	717756824173
Result	✓ Passed
<div>NoticeN/s/f tyre worn on edges</div>	

MOT #1	2013-05-28 10:06
MOT test number	598888643102
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✗  
**MOT**  
  
Expired:  
28 March 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	28 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-04
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2010-06-04	10 mi
Registration #2	2013-05-28	18.440 mi
Registration #3	2014-05-06	23.012 mi
Registration #4	2015-05-05	26.433 mi
Registration #5	2016-05-23	30.666 mi
Registration #6	2016-05-23	30.672 mi
Registration #7	2017-06-07	33.837 mi
Registration #8	2017-06-08	33.838 mi
Registration #9	2018-05-25	36.578 mi
Registration #10	2019-05-20	39.317 mi
Registration #11	2019-05-20	39.322 mi
Registration #12	2019-05-20	39.327 mi
Registration #13	2019-05-20	39.332 mi
Registration #14	2019-05-20	39.337 mi
Registration #15	2019-05-20	39.342 mi
Registration #16	2019-05-20	39.347 mi
Registration #17	2019-05-20	39.352 mi
Registration #18	2019-05-20	39.357 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AU64848