





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-06-26
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-29
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #10	2023-06-30 09:39
MOT test number	562034741130
Result	✓ Passed
Next expiry date	2024-06-29
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Minor Nearside Front Registration plate lamp inoperative in the case of multiple lamps or light sources	
(4.7.1 (b) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #9	2022-06-29 14:21
MOT test number	891170954956
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #8	2021-06-24 15:06
MOT test number	891959957097
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2021-06-24 09:18 MOT test number 769414422603

Result × Failed

Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT test number

328152075384

Result

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front tyre damaged on outer wall and splitting on inner wall

Advice Nearside Front mirrorr glass broken and body loose and likely to become detached

 MOT #5
 2019-04-16 13:55

 MOT test number
 630557681054

 Result
 ✓ Passed

 MOT #4
 2018-04-20 14:25

 MOT test number
 132940403859

 Result
 ✓ Passed

MOT #3 2017-12-06 10:50

MOT test number 288129512950

Advice Offside Front foglamp glass cracked

Advice Offside Rear Nail in tyre

CarCheck.co.uk page 4/12



NX63KVD

report date: 2024-03-29



MOT #1	2016-11-23 11:16
MOT test number	344585905867
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2
Date

Andrie Handrie

Туре

Category

Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-17
Last registration	2023-06-30
Complete history	See info



2013-12-17	7 mi
2016-11-23	44.984 mi
2017-12-06	58.556 mi
2017-12-06	58.556 mi
2018-04-20	61.162 mi
2019-04-16	66.808 mi
	11.777 es
	2016-11-23 2017-12-06 2017-12-06 2018-04-20

More info >

CarCheck.co.uk page 11/12



Car features

S0566

\$0225	Air conditioning

S0225 Air conditioning

S0295

S0482

The VOLKSWAGEN factory car options list is only available in the premium report.

S0501

S0567

S0569

View the complete VOLKSWAGEN factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	CFHC520511