



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Red
Year of manufacture	2006
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-06-26
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-06-25
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-11
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	52
Total items failed	1

MOT #20	2024-03-27 11:34
MOT test number	595812688226
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Odometer unreadable.
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #19**

2024-03-26 09:15

MOT test number

252311968591

Result**✗ Failed**

- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Service & parking brake low on effort.
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Service brake binding but not excessively (1.2.1 (f))

MOT #18

2023-03-22 08:11

MOT test number

939056168371

Result**✓ Passed**

- Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced To subframe mount (6.1.1 (c) (i))
- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced To subframe mount (6.1.1 (c) (i))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #17**

2023-03-20 10:03

MOT test number

648578479299

Result**✗ Failed****MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced To subframe mount (6.1.1 (c) (i))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced To subframe mount (6.1.1 (c) (i))**MOT #16**

2022-04-12 09:26

MOT test number

113597841788

Result**✓ Passed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**MOT #15**

2021-04-12 14:05

MOT test number

118692991198

Result**✓ Passed****Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #14** 2020-03-05 08:31**MOT test number** 934314087229**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2020-03-04 11:32**MOT test number** 731472189839**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2019-02-19 16:23**MOT test number** 831436040128**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11** 2019-02-19 14:52**MOT test number** 745795656509**Result** ✗ Failed**MAJOR** Central Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10** 2018-03-02 11:29**MOT test number** 139475762743**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Outer edge of tyre worn**MOT #9** 2017-02-22 14:47**MOT test number** 531781820814**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Exhaust has a minor leak of exhaust gases badly corroded (7.1.2)**Advice** Offside Rear Tyre worn close to the legal limit bald inside edge (4.1.E.1)**MOT #8** 2016-02-24 14:07**MOT test number** 706726187532**Result** ✓ Passed**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #7** 2015-02-23 15:55**MOT test number** 638554755028**Result** ✓ Passed**MOT #6** 2015-02-18 13:29**MOT test number** 485959945033**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #5** 2014-01-23 15:16**MOT test number** 255823624056**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-10-26 11:47**MOT test number** 157670302351**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-10-21 15:01**MOT test number** 396334891484**Result** ✓ Passed**MOT #2** 2010-05-19 16:21**MOT test number** 353539330170**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2009-09-04 13:50**MOT test number** 930077549271**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	SL56BFZ
Plate since	2019-06-29
Current registration	SL56BFZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-04
Last registration	2024-03-27
Complete history	See info



Registration #1	2006-09-04	16 mi
Registration #2	2009-09-04	24.357 mi
Registration #3	2010-05-19	28.963 mi
Registration #4	2011-10-21	35.042 mi
Registration #5	2012-10-26	39.866 mi
Registration #6	2014-01-23	45.462 mi
Registration #7	2015-02-18	52.749 mi
Registration #8	2015-02-23	52.773 mi
Registration #9	2016-02-24	59.547 mi
Registration #10	2017-02-22	66.964 mi
Registration #11	2018-03-20	75.377 mi
Registration #12	2019-03-20	85.377 mi
Registration #13	2020-03-20	95.377 mi
Registration #14	2021-03-20	105.377 mi
Registration #15	2022-03-20	115.377 mi
Registration #16	2023-03-20	125.377 mi
Registration #17	2024-03-20	135.377 mi
Registration #18	2025-03-20	145.377 mi
Registration #19	2026-03-20	155.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 255340