





report date: 2024-03-29

### General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	2012
Top speed	96 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2022-02-15

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-16
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	17
Total items failed	6

MOT #12	2024-02-07 12:50
MOT test number	612883257945
Result	<b>✓</b> Passed
Next expiry date	2025-02-16

MOT #11		2023-02-08 13:43
MOT test	number	232043863690
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))
Advice	Offside Front Tyre slightly damaged/cracking or perishing in tread of tyre (5.2.	3 (d) (ii))
Advice	Advice Nearside Front Tyre slightly damaged/cracking or perishing in tread of tyre (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))

CarCheck.co.uk page 3/13



MOT #10 2023-02-07 12:17

**MOT test number** 401434827553

Result × Failed

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Tyre slightly damaged/cracking or perishing in tread of tyre (5.2.3 (d) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Nearside Front Tyre slightly damaged/cracking or perishing in tread of tyre (5.2.3 (d) (ii))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #9 2022-02-17 11:45

**MOT test number** 163742351675

**MOT #8** 2021-07-23 09:56

MOT test number 660115832543

**Result** 
✓ Passed

MOT #7 2020-07-24 09:51

**MOT test number** 384705147883

**Advice** Nearside Front Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))

**Advice** Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Front Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



✓ Passed

MOT #6 2019-07-22 11:27

**MOT test number** 642374870265

Result \rightarrow Passed

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2018-07-03 13:33

**MOT test number** 633899475994

Result \( \sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #4 2017-07-26 09:57

MOT test number 687999892946

**Result** ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #3** 2016-07-18 08:45

MOT test number 342544509091

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Items removed from driver's view prior to test

Result

**MOT #2** 2015-07-14 11:40

**MOT test number** 848655895187

**Result** ✓ Passed

CarCheck.co.uk page 5/13



**MOT #1** 2015-07-14 09:45

MOT test number

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	16 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this NISSAN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NIEZ ZIN UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-31
Last registration	2024-02-07
Complete history	See info



Registration #1	2012-07-31	15 mi
Registration #2	2015-07-14	26.828 mi
Registration #3	2015-07-14	26.828 mi
Registration #4	2016-07-18	30.457 mi
Registration #5	2017-07-26	34.044 mi
Registration #6	2018-07-03	36.556 mi
Registration #7	2019-07-22	38.446 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

$\neg$	imer		(			ᅩ
		חשו	ns 1	V 1/1/	reirei	

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

### Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	155933

CarCheck.co.uk page 13/13