



report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND PICASSO BLUEHDI FEEL S/S EAT6
Colour	White
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-05-24
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-05
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	36
Total items failed	18

MOT #8	2023-07-05 16:26
MOT test number	454815710353
Result	✓ Passed
Next expiry date	2024-07-05
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Coolant leak
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #7

2023-07-05 10:01

MOT test number

806520751552

Result

✗ Failed

- Advice** Nearside Rear Nail in tyre
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Front Windscreen washer not working (3.5 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Coolant leak
- Fail** Nearside Body component damaged and likely to cause injury side repeater lens (6.2.1 (a) (i))
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))
- Fail** Offside Front Windscreen washer not working (3.5 (a))
- Advice** Tyre slightly damaged/cracking or perishing both rears and offside front (5.2.3 (d) (ii))

(5.2.3 (d) (i))

Fail Central Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

Fail Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Headlamp aim too low (4.1.2 (a))

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #6** 2022-07-06 15:17**MOT test number** 160045303673**Result** ✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated slightly (6.1.7 (g) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner (5.2.3 (e))

MOT #5 2022-07-05 08:39**MOT test number** 926813333907**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated slightly (6.1.7 (g) (i))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #4	2021-07-02 15:18
---------------	------------------

MOT test number	246146335161
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2021-04-08 14:48
---------------	------------------

MOT test number	247290014458
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2021-04-08 10:21
---------------	------------------

MOT test number	299200204488
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2020-02-08 09:39
---------------	------------------

MOT test number	622107318178
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-22
Last registration	2023-07-05
Complete history	See info



Registration #1	2017-03-22	18 mi
Registration #2	2020-02-08	39.059 mi
Registration #3	2021-04-08	47.111 mi
Registration #4	2021-04-08	47.111 mi
Registration #5	2023-05-22	55.277 mi
Registration #6	2023-05-22	55.277 mi
Registration #7	2023-05-22	55.277 mi
Registration #8	2023-05-22	55.277 mi
Registration #9	2023-05-22	55.277 mi
Registration #10	2023-05-22	55.277 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHD3066007