





report date: 2024-03-28

General information

Make	ТОУОТА
Model	VERSO D-4D ICON
Colour	Blue
Year of manufacture	2016
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 2.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date	2021-02-05	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-09-18
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	6
Total items failed	6

MOT #8	2023-09-19 13:50
MOT test number	340759226514
Result	✓ Passed
Next expiry date	2024-09-18

MOT #	‡ 7	2023-09-18 10:41
MOT t	est number	657160361825
Result	t en	X Failed
Fail	Steering locking device missing split pins missing from both track rod ends (2.1.3	(d))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1	(b) (ii))
Fail	Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))	

MOT #6	2021-12-30 17:02
MOT test number	821269429454
Result	✓ Passed
MOT #5	2021-03-31 09:29
MOT test number	285364158602
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2021-03-25 11:08

MOT test number 403693765986

Result X Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative LIGHT ON (5.2.3 (h))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Macpherson strut mounting damaged and seriously weakened STRUT TOP (5.3.3 (b) (i))

MOT #3 2020-03-09 13:54

MOT test number 410048425871

Result \(\sqrt{Passed} \)

MOT #2 2020-03-09 12:44

MOT test number 631216985085

Result × Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2019-02-12 12:52

MOT test number 107579802726

Result \(\sqrt{Passed} \)

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))

Minor Offside Windscreen wiper blade defective Torn but still clearing screen effectively enough . (3.4 (b)

(i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-04-20
Last registration	2023-09-19
Complete history	See info



Registration #1	2016-04-20	6 mi
Registration #2	2019-02-12	35.162 mi
Registration #3	2020-03-09	54.762 mi
Registration #4	2020-03-09	54.762 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1640 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles 2

Engine number N470649518