





General information

Make	HYUNDAI
Model	I20 MPI SE
Colour	White
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С





Internet history

Entry 2

Date Pictures 2021-01-31

10

Listing price

View report



source: autoonline.co.uk

Entry 1

Date


Pictures

Listing price

2021-01-22 20

View report

LOOKERS SAFE SYSTEM Keeping everyone safe Lookers Fraction





source: yesauto.com



MOT history

MOT expiry date	2024-10-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	2
Total items failed	10

MOT #7	2023-10-26 16:45
MOT test number	623323727573
Result	✓ Passed
Next expiry date	2024-10-25

МОТ #6	2023-10-25 09:16	
MOT test number	315974247460	
Result	🗙 Failed	
Fail Offside Rear Parking (secondary brake) on a single line braking system has no rewheel (1.3.1 (a) (ii))	ecorded effort at a	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Offside Front Headlamp lens seriously defective broken unit (4.1.1 (b) (ii))		
Fail Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire insecure above back box (6.1.3 (e))		
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3)	(h))	

MOT #5	2022-10-19 09:49
MOT test number	468782595660
Result	✓ Passed



SM66FBN report date: 2024-03-28

MOT #	4	2022-10-18 09:18
MOT te	est number	375407316828
Result		🗙 Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #3	2021-10-19 15:14
MOT test number	149089721865
Result	✓ Passed
MOT #2	2020-10-21 15:45
MOT test number	330682332826
Result	✓ Passed
MOT #1	2019-11-08 10:23
MOT test number	381000746298
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	MOT Expires: 25 October 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	25 October 2024
Full MOT history	<u>See MOT history</u>
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

and the second se	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SM66FBN report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-11-30
Last registration	2023-10-26
Complete history	See info



Registration #1	2016-11-30	11 mi
Registration #2	2019-11-08	16.890 mi
Registration #3	2020-10-21	21.159 mi
Registration #4		11.117 esi
Registration #5		11.177 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 esi
Registration #10		11.377 mi

More info >





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1730 mm
Height	1449 mm
Length	4049 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg
Additional information	
Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/11

Engine number

G4LAGM927120