



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Black
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-30
Pictures	31
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-23
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	21
Total items failed	18

MOT #19 2023-10-24 10:57

MOT test number 944209676458

Result ✓ Passed

Next expiry date 2024-10-23

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Advise tyre 2.5mm (5.2.3 (e))

**Advice** Rear Tyre slightly damaged/cracking or perishing Advise both rear tyres perishing / cracking NEAR FAIL (5.2.3 (d) (ii))

**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #18 2022-10-21 10:58

MOT test number 340628428584

Result ✓ Passed

**Advice** Rear Tyre slightly damaged/cracking or perishing Advise both rear tyres showing signs of perishing (5.2.3 (d) (ii))

MOT #17 2021-10-08 18:24

MOT test number 419381161860

Result ✓ Passed

**Advice** Exhaust has a minor leak of exhaust gases has a temporary repair at front (6.1.2 (a))

**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**MOT #16** 2021-10-08 18:24**MOT test number** 145286949514**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Exhaust has a minor leak of exhaust gases has a temporary repair at front (6.1.2 (a))**MOT #15** 2021-01-29 16:00**MOT test number** 246418744453**Result** ✓ Passed**MOT #14** 2019-12-04 13:11**MOT test number** 232927532166**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2018-12-04 12:41**MOT test number** 555242621307**Result** ✓ Passed**MOT #12** 2018-12-04 12:41**MOT test number** 728410030706**Result** ✗ Failed**Pass with rectification** Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Pass with rectification** Front Direction indicator incorrect colour Both (4.4.3 (a))**Pass with rectification** Nearside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))



<b>MOT #11</b>	2017-11-29 14:58
<b>MOT test number</b>	933815894576
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Shock absorber has a light misting of oil (2.7.3)

<b>MOT #10</b>	2017-11-28 11:20
<b>MOT test number</b>	585087264050
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front position lamp(s) not working (1.1.A.3b)
<b>Fail</b>	Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)
<b>Fail</b>	Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)
<b>Advice</b>	Offside Front Shock absorber has a light misting of oil (2.7.3)

<b>MOT #9</b>	2016-11-29 10:13
<b>MOT test number</b>	481893851487
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Worn on edges
<b>Advice</b>	Nearside Rear Perished on sidewall
<b>Advice</b>	Offside Front Worn on edges
<b>Advice</b>	Offside Rear Perished on sidewall

<b>MOT #8</b>	2015-12-03 12:48
<b>MOT test number</b>	242217481300
<b>Result</b>	✓ Passed

**MOT #7** 2015-12-03 12:48**MOT test number** 126957168807**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #6** 2014-11-27 11:34**MOT test number** 427501534403**Result** ✓ Passed**MOT #5** 2014-11-27 11:34**MOT test number** 399931734329**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2013-12-05 12:34**MOT test number** 237029033324**Result** ✓ Passed**MOT #3** 2013-11-30 10:33**MOT test number** 195154333325**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)



MOT #2 2012-12-01 09:31

MOT test number 468266032472

Result ✓ Passed

**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**Notice** Under-trays fitted obscuring some underside components

**Advice** Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-12-01 09:31

MOT test number 249466932302

Result ✗ Failed

**Pass with rectification** Nearside Headlamp aim too low (1.8)

**Advice** Tyre worn close to the legal limit (4.1.E.1)

**Notice** Under-trays fitted obscuring some underside components

**Pass with rectification** Offside Headlamp aim too high (1.8)

**Notice** Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
23 October 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	23 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>KY59NDG</b>
Plate since	2024-03-29
Current registration	<b>KY59NDG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-04
Last registration	2023-10-24
Complete history	<a href="#">See info</a>



Registration #1	2009-12-04	11 mi
Registration #2	2012-12-01	49.391 mi
Registration #3	2013-11-30	60.987 mi
Registration #4	2013-12-05	61.186 mi
Registration #5	2014-11-27	74.149 mi
Registration #6	2015-12-03	79.098 mi
Registration #7	2015-12-03	79.098 mi
Registration #8	2016-11-29	83.908 mi
Registration #9	2017-11-28	89.589 mi
Registration #10	2017-11-29	89.600 mi
Registration #11	2018-11-29	95.277 mi
Registration #12	2019-11-29	95.277 mi
Registration #13	2020-11-29	95.277 mi
Registration #14	2021-11-29	95.277 mi
Registration #15	2022-11-29	95.277 mi
Registration #16	2023-11-29	95.277 mi
Registration #17	2024-11-29	95.277 mi
Registration #18	2025-11-29	95.277 mi
Registration #19	2026-11-29	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629