





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	I20 MPI S AIR BLUE DRIVE
Colour	White
Year of manufacture	2016
Top speed	99 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	74 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	70.6 mpg
Consumption combined	58.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	1

MOT #7	2023-10-16 10:11
MOT test number	677295708654
Result	✓ Passed
Next expiry date	2024-10-21
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6		2022-10-21 08:50
MOT test	number	614359721392
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front driving light not working ( broken wiring )	

MOT #5		2021-09-24 16:14
MOT test	number	378089471214
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**MOT #4** 2021-09-24 11:21

**MOT test number** 165633007542

Result × Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2020-10-22 10:40

MOT test number 990768465550

Result \square Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2020-10-22 10:40

MOT test number 215468645009

Result × Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #1		2019-08-15 08:48
MOT test	number	200856952380
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Undertray not fully secure (8.1.1 (b) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	21 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



**EY66XAF** 

report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

EY66XAF

More info >

report date: 2024-03-28

# Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HYUNDAI had different number plates. about of pliates

CarCheck.co.uk page 9/12



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-06
Last registration	2023-10-16
Complete history	See info



Registration #1	2016-09-06	6 mi
Registration #2	2019-08-15	39.797 mi
Registration #3	2020-10-22	48.973 mi
Registration #4	2020-10-22	48.973 mi
Registration #5		11.177 es
Registration #6		71.777 es
Registration #7		11.177 es
Registration #8		11.777 es
Registration #9		11.777 no

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



## Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

**Engine number** G4LAFM830343