





report date: 2024-03-28

### General information

Make	SUZUKI
Model	ALTO SZ
Colour	Blue
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-06-12

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## MOT history

MOT expiry date	2024-08-06
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	14
Total items failed	0

MOT #9		2023-07-31 09:49
MOT test	number	671805969643
Result		<b>✓</b> Passed
Next expi	ry date	2024-08-06
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (	5.3.3 (b) (i))
Advice (c))	Nearside Front Outer Brake pipe corroded, covered in grease or other	material corroding (1.1.11
Advice (c))	Nearside Rear Inner Brake pipe corroded, covered in grease or other n	naterial corroded (1.1.11
Advice	Items removed from driver's view prior to test hanging on interior mirr	ror
Advice	Offside Rear Outer Brake pipe corroded, covered in grease or other ma	aterial corroded (1.1.11 (c))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5	3.3 (b) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Outer Brake pipe corroded, covered in grease or other m	aterial corroded (1.1.11 (c))
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other ma	aterial corroded (1.1.11 (c))
Advice (c))	Nearside Rear Outer Brake pipe corroded, covered in grease or other r	material corroded (1.1.11

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8		2022-07-25 09:48
MOT test	number	150136975531
Result		✓ Passed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Rear Outer Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))		
Advice	Rear Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))	

MOT #7	2021-08-07 06:45
MOT test number	100607949237
Result	<b>✓</b> Passed
MOT #6	2021-06-11 09:13
MOT test number	279750568016
Result	<b>✓</b> Passed
MOT #5	2020-12-21 10:51
MOT test number	137274501507
Result	<b>✓</b> Passed
Advice Offside Rear bumper damaged	

MOT #4	2019-06-26 15:17
MOT test number	944057075137
Result	<b>✓</b> Passed
MOT #3	2018-06-21 13:28
MOT test number	132605042498
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2	2017-06-13 10:42
MOT test number	491234200276
Result	<b>✓</b> Passed
MOT #1	2016-06-23 12:53
MOT test number	462891735685
Mor test number	402091733003

CarCheck.co.uk page 5/12



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	6 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra SUZUKI salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

e when miscory	
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full research	
********	
***************************************	
***************************************	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	AIR SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-27
Last registration	2023-07-31
Complete history	See info



Registration #1	2013-06-27	25 mi
Registration #2	2016-06-23	6.893 mi
Registration #3	2017-06-13	7.542 mi
Registration #4	2018-06-21	8.061 mi
Registration #5	2019-06-26	8.446 mi
Registration #6	2020-12-21	11.971 mi
Registration #7		11.777 es
Registration #8		0.074
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



## Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1640153

CarCheck.co.uk page 12/12