





General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	Н







Internet history

Date Pictures 2022-04-03

50

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	17
Total items failed	0

МОТ #8	2023-09-25 11:43
MOT test number	656268411245
Result	✓ Passed
Next expiry date	2024-10-04
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excess ARM (5.3.4 (a) (i))	sive movement TRAILING
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in exce TRAILING ARM (5.3.4 (a) (i))	essive movement
Advice Offside Power steering component has slight seepage from a component (a))	STEERING RACK (2.1.5
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	



С	U	6	3	V	V	R	
	rep	ort	dat	e:	202	4-03	3-29

MOT #7		2022-09-30 11:04
MOT test	number	426401071018
Result		✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Power steering component has slight seepage from a component RACK (2.1.5 (a))

MOT #6	2021-10-01 09:34
MOT test number	592268250104
Result	✓ Passed

MOT #5	2020-09-26 11:23
MOT test number	641114673795
Result	✓ Passed
MOT #4	2019-09-21 11:22

МОТ #4	2019-09-21 11:22
MOT test number	584329763058
Result	✓ Passed
MinorOffside Rear Registration plate lamp inoperative in the case of multiple lamp(4.7.1 (b) (i))AdviceNearside Rear Child Seat fitted not allowing full inspection of adult belt	os or light sources

МОТ #3	2018-09-29 10:25
MOT test number	601550522084
Result	✓ Passed



MOT #2	2017-10-02 09:20
MOT test number	640735460036
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin n/s + o/s (3.5.1g)	
Advice Front Brake pad(s) wearing thin n/s + o/s (3.5.1g)	

MOT #1	2016-10-05 10:16
MOT test number	515009456704
Result	✓ Passed





Tax & MOT check

✓ Taxe Tax due:	ed	Expires:	✓ MOT
1 October 2024 Tax status		4 October 2024	Valid until 1 October
Days left			155
MOT expiry date			4 October 2024
Full MOT history			<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-10-04
Last registration	2023-09-25
Complete history	See info



Registration #1	2013-10-04	15 mi
Registration #2	2016-10-05	18.117 mi
Registration #3	2017-10-02	25.894 mi
Registration #4	2018-09-29	31.650 mi
Registration #5	2019-09-21	37.003 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.317 mi

More info >





Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg
Additional information	
Additional information Fuel tank capacity	65 l
	65 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5