





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 VERVE
Colour	Red
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP	
Max. torque	93 Nm at 3.600 rpm	
Engine capacity	998 сс	
Cylinders	3	
Fuel type	Petrol	
Consumption city	51.4 mpg	
Consumption extra urban	72.4 mpg	
Consumption combined	62.8 mpg	
CO2 emission	106 g/km	
CO2 label	В	



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2021-07-21
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	28
Total items failed	2

MOT #11		2020-06-22 12:16
MOT test	number	167929818904
Result		✓ Passed
Next expi	ry date	2021-07-21
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust has a minor leak of exhaust gases Clamp (6.1.2 (a))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10		2019-07-22 16:41
MOT test	number	371513615451
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT #9 2018-07-17 12:48

MOT test number 611347653686

Result ✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-07-17 08:24

MOT test number 176214402274

Result X Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Hand brake has little to no reserve travel

MOT test number

Result

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Hand brake has little to no reserve travel

MOT #5

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #4
 2015-07-09 14:23

 MOT test number
 608100895173

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3		2014-07-12 11:15
MOT test	number	758653794183
Result		✓ Passed
Notice	Both rear tyres tread cracked	
Notice	Items removed from driver's view prior to test	

Notice Items removed from driver's view prior to test	
MOT #2	2013-07-02 12:44
MOT test number	165973183137
Result	✓ Passed
MOT #1	2012-12-11 13:05
MOT test number	108026642304
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax expired: 10 December 2020

X MOT

Expired: 21 July 2021

Tax status Expired at 10 December 2020

Days left 1237 days too late

MOT expiry date 21 July 2021

Full MOT history See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-12-16
Last registration	2020-06-22
Complete history	See info



Registration #1	2009-12-16	9 mi
Registration #2	2012-12-11	20.060 mi
Registration #3	2013-07-02	24.866 mi
Registration #4	2014-07-12	31.515 mi
Registration #5	2015-07-09	37.172 mi
Registration #6	2016-07-22	42.132 mi
Registration #7		11.777 es
Registration #8		11.117 es
Registration #9		11.777 es
Registration #10		11.117 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	875 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 6218893