



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI
Colour	Grey
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 4


Date	2021-10-22
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 3


Date	2021-10-15
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-09-30
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1


Date	2021-09-16
------	------------

Pictures

12

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #14	2022-10-07 12:41
MOT test number	909809701580
Result	✓ Passed
Next expiry date	2023-10-06
Advice	Nearside Brake cable damaged but not to excess (1.1.15 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2022-10-05 11:12
MOT test number	667016400228
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Brake cable damaged but not to excess (1.1.15 (a))
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #12	2021-09-16 12:49
MOT test number	639505185877
Result	✓ Passed

MOT #11	2020-09-17 09:32
MOT test number	283768039532
Result	✓ Passed
Advice	Exhaust system corroded

**MOT #10** 2020-09-17 09:32**MOT test number** 686502921964**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Exhaust system corroded**MOT #9** 2019-09-27 09:01**MOT test number** 263670250917**Result** ✓ Passed**MOT #8** 2018-09-21 13:31**MOT test number** 634609285430**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #7** 2018-09-21 09:51**MOT test number** 524158421017**Result** ✗ Failed**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #6** 2017-09-27 12:03**MOT test number** 538541374628**Result** ✓ Passed

- Advice** Rear exhaust mount broken
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear exhaust heat shield loose
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2016-09-27 10:23**MOT test number** 838303227383**Result** ✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2015-09-25 10:19**MOT test number** 389586112717**Result** ✓ Passed

- Advice** Offside Front brake discs rusted
- Advice** Child seat fitted in rear

MOT #3 2014-09-26 10:32**MOT test number** 965459164269**Result** ✓ Passed

- Notice** Front brake discs corroded



MOT #22013-09-06 09:40

MOT test number659819743260

Result

Passed

- NoticeUnder-trays fitted obscuring some underside components
- NoticeItems removed from driver's view prior to test
- NoticeOffside rear tyre cut (not deep enough to reach ply or cord)
- NoticeEngine covers fitted obscuring some components in the engine bay
- NoticeNearside front tyre cut (not deep enough to reach ply or cord)

MOT #12012-09-25 11:37

MOT test number437139662263

Result

Passed

- AdviceFront Tyre worn close to the legal limit (4.1.E.1)
- NoticeRear tyres out of shape



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YH59MVM
Plate since	2019-09-29
Current registration	YH59MVM
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-29
Last registration	2022-10-07
Complete history	See info



Registration #1	2009-09-29	7 mi
Registration #2	2012-09-25	31.903 mi
Registration #3	2013-09-06	58.851 mi
Registration #4	2014-09-26	75.871 mi
Registration #5	2015-09-25	84.578 mi
Registration #6	2016-09-27	94.455 mi
Registration #7	2017-09-27	104.167 mi
Registration #8	2018-09-21	111.819 mi
Registration #9	2018-09-21	111.827 mi
Registration #10	2019-09-27	117.321 mi
Registration #11	2019-09-27	117.321 mi
Registration #12	2019-09-27	117.321 mi
Registration #13	2019-09-27	117.321 mi
Registration #14	2019-09-27	117.321 mi
Registration #15	2019-09-27	117.321 mi
Registration #16	2019-09-27	117.321 mi
Registration #17	2019-09-27	117.321 mi
Registration #18	2019-09-27	117.321 mi
Registration #19	2019-09-27	117.321 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1580 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9B00180
---------------	---------