



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SE
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-25
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	29
Total items failed	0

MOT #14	2023-06-26 13:32
MOT test number	991797261632
Result	✓ Passed
Next expiry date	2024-07-05
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Wear in o/s and n/s front suspension arm rear bushes

MOT #13	2022-07-06 14:04
MOT test number	536059858719
Result	✓ Passed

MOT #12	2022-02-04 17:04
MOT test number	531975442356
Result	✓ Passed
Advice	Perishing nail n/s/r tyre inner tread. nail in n/s/f tyre.

MOT #11	2022-02-04 15:04
MOT test number	984622186772
Result	✗ Failed
Advice	Perishing nail n/s/r tyre inner tread. nail in n/s/f tyre.
MAJOR	Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tread (5.2.3 (d) (i))

**MOT #10** 2021-02-16 10:53**MOT test number** 855985054755**Result** ✓ Passed**Advice** Nearside Head light output reduced**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Nearside + offside front lower rear (5.3.4 (a) (i))**Advice** Service overdue**MOT #9** 2021-02-12 14:47**MOT test number** 229839158971**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Nearside Head light output reduced**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Nearside + offside front lower rear (5.3.4 (a) (i))**Advice** Service overdue**MOT #8** 2020-02-18 17:26**MOT test number** 339737741819**Result** ✓ Passed**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**MOT #7** 2019-02-21 19:22**MOT test number** 119367561883**Result** ✓ Passed**MOT #6** 2018-01-03 12:23**MOT test number** 577985380965**Result** ✓ Passed

**MOT #5** 2017-01-31 11:02**MOT test number** 794905295451**Result** ✓ Passed**Advice** Small chips in windscreen)(exhaust rusty**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2016-01-07 10:23**MOT test number** 322676776448**Result** ✓ Passed**Advice** Offside Rear Tyre perished**Advice** Chips in screen. exhaust rusty. diesel smoke output high**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #3** 2015-03-24 12:27**MOT test number** 319133985033**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Notice** Exhaust rusty**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Chips in windscreen



MOT #2 2014-03-18 08:56

MOT test number 265447274061

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Exhaust corroded

Notice Chips in windscreen

Notice Engine covers fitted obscuring some components in the engine bay

MOT #1 2013-03-19 08:37

MOT test number 318848873037

Result ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RK10YTR
Plate since	2019-09-29
Current registration	RK10YTR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-30
Last registration	2023-06-26
Complete history	See info



Registration #1	2010-03-30	10 mi
Registration #2	2013-03-19	24.350 mi
Registration #3	2014-03-18	26.993 mi
Registration #4	2015-03-24	29.902 mi
Registration #5	2016-01-07	31.346 mi
Registration #6	2017-01-31	32.805 mi
Registration #7	2018-01-03	37.491 mi
Registration #8	2019-02-21	61.288 mi
Registration #9	2020-03-20	65.377 mi
Registration #10	2021-03-20	65.377 mi
Registration #11	2022-03-20	65.377 mi
Registration #12	2023-03-20	65.377 mi
Registration #13	2024-03-20	65.377 mi
Registration #14	2025-03-20	65.377 mi
Registration #15	2026-03-20	65.377 mi
Registration #16	2027-03-20	65.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	768432