



report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO DYNAMIC
Colour	Red
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E







## Internet history

### Entry 3

Date 2021-12-27

Pictures 9

Listing price [View report](#)




source: autotrader.co.uk

### Entry 2

Date 2021-12-13

Pictures 9

Listing price [View report](#)




source: autotrader.co.uk

### Entry 1

Date 2021-11-09

Pictures 9

Listing price [View report](#)



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-13
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	3

MOT #16	2024-03-14 19:41
MOT test number	341641213773
Result	✓ Passed
Next expiry date	2025-03-13

MOT #15	2022-11-25 17:53
MOT test number	810069096922
Result	✓ Passed
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #14	2022-11-24 09:10
MOT test number	984458038728
Result	✗ Failed
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords and tread down to 1.6mm (5.2.3 (d) (i))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #13** 2021-12-18 13:17**MOT test number** 203425574929**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Rear Shock absorbers has light misting of oil both side (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2021-12-18 13:17**MOT test number** 418109088001**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Rear Shock absorbers has light misting of oil both side (5.3.2 (b))**MOT #11** 2020-10-14 13:27**MOT test number** 644607492545**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and outer wall chipped slight damage (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-11-04 09:38**MOT test number** 586669829517**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2019-11-04 09:38**MOT test number** 595493001864**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8** 2018-11-05 13:33**MOT test number** 520840941517**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-10-13 13:08**MOT test number** 870283459583**Result** ✓ Passed**MOT #6** 2016-11-02 11:55**MOT test number** 490494616782**Result** ✓ Passed**MOT #5** 2015-11-03 10:12**MOT test number** 884762072864**Result** ✓ Passed**MOT #4** 2014-11-03 15:13**MOT test number** 636357904308**Result** ✓ Passed



MOT #3	2014-11-03 10:39
MOT test number	229837904325
Result	✗ Failed
<div><div>Fail</div>Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)</div>	

MOT #2	2013-11-05 12:02
MOT test number	445829103462
Result	✓ Passed

MOT #1	2012-11-05 11:18
MOT test number	388410412311
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-02
Last registration	2024-03-14
Complete history	<a href="#">See info</a>



Registration #1	2009-11-02	12 mi
Registration #2	2012-11-05	7.699 mi
Registration #3	2013-11-05	14.318 mi
Registration #4	2014-11-03	19.605 mi
Registration #5	2014-11-03	19.605 mi
Registration #6	2015-11-03	24.638 mi
Registration #7	2016-11-02	31.324 mi
Registration #8	2017-10-13	36.955 mi
Registration #9	2018-11-05	43.501 mi
Registration #10	2019-11-04	50.358 mi
Registration #11	2020-03-29	50.358 mi
Registration #12	2020-03-29	50.358 mi
Registration #13	2020-03-29	50.358 mi
Registration #14	2020-03-29	50.358 mi
Registration #15	2020-03-29	50.358 mi
Registration #16	2020-03-29	50.358 mi
Registration #17	2020-03-29	50.358 mi
Registration #18	2020-03-29	50.358 mi
Registration #19	2020-03-29	50.358 mi
Registration #20	2020-03-29	50.358 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4924076