



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.5 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.1 mpg



LABEL UNKNOWN

**MOT history**

MOT #18	2020-08-03 09:31
MOT test number	955327178201
Result	✓ Passed
Next expiry date	2021-08-02

MOT #17	2020-07-29 08:27
MOT test number	401144607678
Result	✗ Failed
Fail Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))	
Fail Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))	

MOT #16	2019-04-01 08:34
MOT test number	685975296713
Result	✓ Passed

MOT #15	2019-04-01 08:34
MOT test number	897486360784
Result	✗ Failed
Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #14	2018-04-10 09:04
MOT test number	705009503283
Result	✓ Passed

MOT #13	2017-03-22 14:26
MOT test number	451456811395
Result	✓ Passed

**MOT #12** 2016-03-04 16:27**MOT test number** 330387487717**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)**MOT #11** 2016-03-04 16:01**MOT test number** 507478040063**Result** ✗ Failed**Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)**MOT #10** 2014-12-12 11:51**MOT test number** 407676244486**Result** ✓ Passed

**MOT #9** 2014-09-18 14:30**MOT test number** 288701964250**Result** ✓ Passed**Notice** N/s front tyre cracking**Notice** Exhaust heatshield rattling**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Condensation in o/s side repeater**Notice** O/s front tyre cracking**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-09-26 09:15**MOT test number** 967639063216**Result** ✓ Passed**MOT #7** 2012-09-25 12:07**MOT test number** 586329362219**Result** ✓ Passed**MOT #6** 2012-09-24 13:23**MOT test number** 145908562259**Result** ✗ Failed**Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #5** 2011-09-26 09:34**MOT test number** 655389661256**Result** ✓ Passed**MOT #4** 2010-09-30 12:15**MOT test number** 752113470244**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-11-06 09:54**MOT test number** 460261618484**Result** ✓ Passed**MOT #2** 2008-11-05 09:54**MOT test number** 473730518491**Result** ✗ Failed**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Notice** Engine under tray insecure at rear.**Fail** Centre Exhaust system not adequately supported (7.1.1)**Fail** Nearside Front brake disc excessively pitted (3.5.1h)**MOT #1** 2007-11-15 11:00**MOT test number** 483729317424**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 YC54YEL
Plate since	2019-03-29
Current registration	 YC54YEL
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-10-22
Last registration	2020-08-03
Complete history	See info



Registration #1	2004-10-22	13 mi
Registration #2	2007-11-15	19.720 mi
Registration #3	2008-11-05	26.348 mi
Registration #4	2008-11-06	26.377 mi
Registration #5	2010-09-30	34.725 mi
Registration #6	2011-09-26	38.173 mi
Registration #7	2012-09-24	44.191 mi
Registration #8	2012-09-25	44.191 mi
Registration #9	2013-09-26	48.917 mi
Registration #10	2014-09-18	52.638 mi
Registration #11	2015-09-20	56.359 mi
Registration #12	2016-09-20	60.080 mi
Registration #13	2017-09-20	63.801 mi
Registration #14	2018-09-20	67.522 mi
Registration #15	2019-09-20	71.243 mi
Registration #16	2020-08-03	74.964 mi
Registration #17	2021-08-03	78.685 mi
Registration #18	2022-08-03	82.406 mi
Registration #19	2023-08-03	86.127 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	3

Number of axles

2

Engine number

AZJ725872