



RENAULT

Y6630GM

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE SCENIC AUTHENTIQUE 16V SCENIC
Colour	Red
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 1

Date	2021-08-28
Pictures	1



source: cargurus.co.uk

**MOT history**

MOT #27	2022-10-26 09:56
MOT test number	305754895462
Result	✓ Passed
Next expiry date	2023-11-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge 185/65x15 Inner edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 185/65x15 inner edge (5.2.3 (e))

MOT #26	2022-10-26 07:58
MOT test number	938247029183
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 185/65x15 Inner edge (5.2.3 (e))
Fail	Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 185/65x15 inner edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #25	2021-11-04 18:18
MOT test number	199772164833
Result	✓ Passed
Advice	Rear All direction indicators slightly discoloured both rear indicators (4.4.3 (a))

MOT #24	2020-11-19 17:52
MOT test number	844407629736
Result	✓ Passed

**MOT #23** 2020-11-18 15:43**MOT test number** 754705933836**Result** ✗ Failed

- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #22 2019-11-05 14:17**MOT test number** 643221632335**Result** ✓ Passed**MOT #21** 2018-11-15 16:52**MOT test number** 575903448818**Result** ✓ Passed**MOT #20** 2018-11-14 15:20**MOT test number** 156846713807**Result** ✗ Failed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MOT #19 2017-11-22 17:07**MOT test number** 424422736442**Result** ✓ Passed

**MOT #18** 2016-11-16 09:32**MOT test number** 373737927152**Result** ✓ Passed**MOT #17** 2015-11-12 12:23**MOT test number** 781038271030**Result** ✓ Passed**MOT #16** 2015-11-11 17:25**MOT test number** 670273764129**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #15** 2014-11-18 08:59**MOT test number** 179522324315**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14** 2013-11-12 12:41**MOT test number** 597856413330**Result** ✓ Passed**MOT #13** 2012-11-15 11:02**MOT test number** 376890822335**Result** ✓ Passed**MOT #12** 2011-11-16 13:42**MOT test number** 477170521336**Result** ✓ Passed

**MOT #11** 2011-11-16 13:42**MOT test number** 705340221325**Result** ✗ Failed

Pass with rectification Offside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

MOT #10 2010-11-03 17:24**MOT test number** 991347700385**Result** ✓ Passed**MOT #9** 2010-11-03 09:45**MOT test number** 474007600439**Result** ✗ Failed

Notice Nearside and offside rear brake discs - excessively scored and pitted on the inner face

Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #8 2009-11-10 16:41**MOT test number** 442234819405**Result** ✓ Passed**MOT #7** 2009-11-10 09:15**MOT test number** 420094419393**Result** ✗ Failed

Fail Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

**MOT #6** 2008-11-25 16:50**MOT test number** 183910738365**Result** ✓ Passed**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**MOT #5** 2008-11-25 16:50**MOT test number** 502080538304**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**MOT #4** 2008-02-29 11:25**MOT test number** 152400168474**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Rear brake disc slightly pitted (3.5.1h)



MOT #3 2007-02-13 15:40

MOT test number 910604247092

Result ✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2006-02-20 11:54

MOT test number 952011156031

Result ✓ Passed

MOT #1 2006-02-15 14:46

MOT test number 874076746089

Result ✗ Failed

Fail Offside front brake binding (3.7.B.1)

Fail An item not tested (Manual)

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside front brake binding (3.7.B.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	Y663OGM
Plate since	2019-03-29
Current registration	Y663OGM
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2001-03-06
Last registration	2022-10-26
Complete history	See info



Registration #1	2001-03-06	11 mi
Registration #2	2006-02-15	37.487 mi
Registration #3	2006-02-20	37.547 mi
Registration #4	2007-02-13	40.964 mi
Registration #5	2008-02-29	45.234 mi
Registration #6	2008-11-25	48.320 mi
Registration #7	2009-11-10	53.264 mi
Registration #8	2009-11-10	53.264 mi
Registration #9	2010-11-03	60.162 mi
Registration #10	2010-11-03	60.162 mi
Registration #11	2011-11-16	68.243 mi
Registration #12	2012-11-15	74.625 mi
Registration #13	2013-11-12	76.968 mi
Registration #14	2014-11-18	79.908 mi
Registration #15	2015-11-18	82.849 mi
Registration #16	2016-11-18	85.790 mi
Registration #17	2017-11-18	88.731 mi
Registration #18	2018-11-18	91.672 mi
Registration #19	2019-11-18	94.613 mi
Registration #20	2020-11-18	97.554 mi
Registration #21	2021-11-18	100.495 mi
Registration #22	2022-10-26	103.436 mi
Registration #23	2022-10-26	103.436 mi
Registration #24	2022-10-26	103.436 mi
Registration #25	2022-10-26	103.436 mi
Registration #26	2022-10-26	103.436 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D613127