



General information

Make	VOLKSWAGEN
Model	EOS S TSI
Colour	Black
Year of manufacture	2010
Top speed	124 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	144 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-08-13
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-23
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	22
Total items failed	6

MOT #14	2023-08-21 14:57
MOT test number	362553518826
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13**

2023-08-21 09:47

**MOT test number**

798753436668

**Result****✗ Failed****Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #12**

2022-08-24 10:48

**MOT test number**

579433026797

**Result****✓ Passed****Advice** Rear Anti-roll bar linkage corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Anti-roll bar linkage corroded but not seriously weakened Both sides (5.3.3 (b) (i))**Advice** Rear Wishbone arms corroded**Advice** Front Shock absorbers has light misting of oil Both sides (5.3.2 (b))**MOT #11**

2021-08-09 11:33

**MOT test number**

838965529919

**Result****✓ Passed**

**MOT #10**

2021-07-31 14:53

**MOT test number**

719064370591

**Result**

✗ Failed

**Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Registration plate missing (0.1 (a))**Fail** Rear Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))**MOT #9**

2020-07-30 09:35

**MOT test number**

217199785135

**Result**

✓ Passed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge very close ! (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2019-08-17 07:54

**MOT test number**

573682161560

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2018-08-06 08:48

**MOT test number**

199555805867

**Result**

✓ Passed



<b>MOT #6</b>	2017-08-04 07:59
<b>MOT test number</b>	537891787504
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2016-08-18 08:19
<b>MOT test number</b>	416923203055
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2015-08-22 08:47
<b>MOT test number</b>	639899690788
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2014-07-23 14:59
<b>MOT test number</b>	885464804238
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2013-08-14 11:41
<b>MOT test number</b>	127746323230
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2013-07-09 15:37
<b>MOT test number</b>	445550793172
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
23 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	23 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-29
Last registration	2023-08-21
Complete history	<a href="#">See info</a>



Registration #1	2010-06-29	27 mi
Registration #2	2013-07-09	15.115 mi
Registration #3	2013-08-14	15.135 mi
Registration #4	2014-07-23	23.962 mi
Registration #5	2015-08-22	37.465 mi
Registration #6	2016-08-18	45.997 mi
Registration #7	2017-08-04	53.105 mi
Registration #8	2018-08-06	60.908 mi
Registration #9	2019-08-06	68.710 mi
Registration #10	2020-08-06	76.512 mi
Registration #11	2021-08-06	84.314 mi
Registration #12	2022-08-06	92.116 mi
Registration #13	2023-08-06	100.000 mi
Registration #14	2024-03-28	107.884 mi
Registration #15		
Registration #16		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1215 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CAX 539598