



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Beige
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-08-06
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-04
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	21
Total items failed	2

MOT #13	2023-09-02 15:03
MOT test number	417803162338
Result	✓ Passed
Next expiry date	2024-09-01

MOT #12	2023-09-02 14:18
MOT test number	959646566194
Result	✗ Failed
<div><div>DANGEROUS</div>Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))</div>	
<div><div>MAJOR</div>Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))</div>	
<div><div>MAJOR</div>Offside Rear Inner Position lamp not working (4.2.1 (a) (ii))</div>	
<div><div>Advice</div>Nearside Front Tyre worn close to legal limit/worn on edge Inner shoulder (5.2.3 (e))</div>	
<div><div>MAJOR</div>Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))</div>	

**MOT #11**

2022-08-31 09:13

**MOT test number**

284813211190

**Result**

✓ Passed

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Brake disc surface rusty in places. (1.1.14 (a) (ii))

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Central Parking brake lever defective but can be satisfactorily operated Release knob is not secure (1.1.6 (d))

**Advice** Central Rear Seat belt buckle slightly damaged Centre row centre belt buckle cover missing (7.1.2 (d))

**Advice** Offside Brake disc worn, pitted or scored, but not seriously weakened Brake disc surface rusty in places. (1.1.14 (a) (ii))

**MOT #10**

2022-08-30 14:57

**MOT test number**

301780447239

**Result**

✗ Failed

**Advice** Central Rear Seat belt buckle slightly damaged Centre row centre belt buckle cover missing (7.1.2 (d))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Brake disc surface rusty in places. (1.1.14 (a) (ii))

**Advice** Central Parking brake lever defective but can be satisfactorily operated Release knob is not secure (1.1.6 (d))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre worn badly on inner edge (5.2.3 (e))

**MAJOR** Rear Registration plate inscription illegible (0.1 (b))

**Advice** Offside Brake disc worn, pitted or scored, but not seriously weakened Brake disc surface rusty in places. (1.1.14 (a) (ii))

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn badly on inner edge (5.2.3 (e))

**MOT #9**

2021-09-01 14:26

**MOT test number**

484050914432

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #8** 2020-09-29 11:43**MOT test number** 242926827491**Result** ✓ Passed**MOT #7** 2019-09-23 11:37**MOT test number** 184881553045**Result** ✓ Passed**MOT #6** 2019-09-23 10:42**MOT test number** 231698200397**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2018-10-03 10:27**MOT test number** 752323679426**Result** ✓ Passed**MOT #4** 2017-10-04 15:49**MOT test number** 526123005329**Result** ✓ Passed**MOT #3** 2017-10-04 09:54**MOT test number** 541863154681**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2016-10-05 11:03**MOT test number** 450046309089**Result** ✓ Passed



MOT #1	2015-10-12 07:25
MOT test number	972746133433
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
1 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	1 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-10-15
Last registration	2023-09-02
Complete history	<a href="#">See info</a>



Registration #1	2012-10-15	25 mi
Registration #2	2015-10-12	26.776 mi
Registration #3	2016-10-05	29.017 mi
Registration #4	2017-10-04	32.214 mi
Registration #5	2017-10-04	32.218 mi
Registration #6	2018-10-03	36.759 mi
Registration #7	2019-09-23	39.923 mi
Registration #8	2019-09-23	39.925 mi
Registration #9	2019-09-23	39.925 mi
Registration #10	2019-09-23	39.925 mi
Registration #11	2019-09-23	39.925 mi
Registration #12	2019-09-23	39.925 mi
Registration #13	2019-09-23	39.925 mi
Registration #14	2019-09-23	39.925 mi
Registration #15	2019-09-23	39.925 mi
Registration #16	2019-09-23	39.925 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1544 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CAYCP75763