



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Purple
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A








Internet history

Entry 1

Date	2021-07-18
Pictures	32
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-14
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	35
Total items failed	2

MOT #16	2023-06-21 09:06
MOT test number	103646256481
Result	✓ Passed
Next expiry date	2024-07-14

MOT #15	2022-06-20 12:25
MOT test number	852097633034
Result	✓ Passed
Advice	Horn slightly distort

MOT #14	2021-07-15 17:58
MOT test number	323249914436
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13**

2020-12-02 10:43

MOT test number

832638831019

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12**

2019-11-26 09:07

MOT test number

192151566455

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2019-11-26 09:07

MOT test number

709487126097

Result

✗ Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2018-12-03 16:47

MOT test number

399560124409

Result

✓ Passed



MOT #9	2018-12-03 15:02
MOT test number	972757225530
Result	✗ Failed
DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #8	2018-06-18 16:06
MOT test number	331088894884
Result	✓ Passed
Advice Front Lower both lower wing,sills damaged	
Advice Offside Rear bumper slightly loose	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Advice Rear wiper split	

MOT #7	2018-06-18 10:51
MOT test number	155080486537
Result	✗ Failed
MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))	
MAJOR Nearside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))	
Advice Rear wiper split	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Advice Both front lower sill,wings corroded	
MAJOR Windscreen wiper does not clear the windscreen effectively NOT CHECKED DUE TO WASHERS (3.4 (b) (ii))	
Advice Offside Rear bumper slightly loose	
MAJOR Offside Front Brake pipe excessively corroded to rear at rear (1.1.11 (c))	

**MOT #6** 2017-06-23 12:50**MOT test number** 651227602582**Result** ✓ Passed**Advice** Damage to both front lower wings**MOT #5** 2016-07-08 15:20**MOT test number** 888349432375**Result** ✓ Passed**Advice** Front damage to lower front wings**MOT #4** 2015-06-04 12:27**MOT test number** 165825055120**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight damage to nsf and osf lower front wings**MOT #3** 2015-06-04 10:37**MOT test number** 209075355165**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Slight damage to nsf and osf lower front wings**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-06-23 12:23
MOT test number	429204874183
Result	✓ Passed
Notice	Both front lower wings slight damage

MOT #1	2013-06-13 14:14
MOT test number	236854963480
Result	✓ Passed
Notice	Damage to nsf lower wing/sill



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
14 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-21
Last registration	2023-06-21
Complete history	See info



Registration #1	2010-06-21	24 mi
Registration #2	2013-06-13	29.113 mi
Registration #3	2014-06-23	33.489 mi
Registration #4	2015-06-04	39.021 mi
Registration #5	2015-06-04	39.021 mi
Registration #6	2016-07-08	44.475 mi
Registration #7	2017-06-23	48.760 mi
Registration #8	2018-06-18	53.030 mi
Registration #9	2018-06-18	53.030 mi
Registration #10	2019-06-21	55.377 mi
Registration #11	2019-06-21	55.377 mi
Registration #12	2019-06-21	55.377 mi
Registration #13	2019-06-21	55.377 mi
Registration #14	2019-06-21	55.377 mi
Registration #15	2019-06-21	55.377 mi
Registration #16	2019-06-21	55.377 mi
Registration #17	2019-06-21	55.377 mi
Registration #18	2019-06-21	55.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	1KR0998678
---------------	------------