






report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER HARD TOP
Colour	Blue
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	27.4 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date	2021-11-09	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-06
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #15	2024-02-06 10:24
MOT test number	518304628302
Result	✓ Passed
Next expiry date	2025-02-06
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Offside Power steering component has slight seepage from a component box (2.1.5 (a))	

MOT #14		2023-02-07 15:58
MOT test	number	461314905421
Result		✓ Passed
Advice	Power steering component has slight seepage from a component steer	ing box (2.1.5 (a))

MOT #13	2022-01-21 12:26
MOT test number	745846511715
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2021-11-22 12:18

MOT test number 364193283607

Result ✓ Passed

Minor

Steering box leaking oil (2.1.1 (e) (i))

Advice

Rear Registration plate deteriorated but not likely to be misread number plate has slight damage

(0.1 (b))

MOT #11 2021-11-18 14:51

MOT test number 875337822544

Result X Failed

MAJOR Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Minor Steering box leaking oil (2.1.1 (e) (i))

MAJOR Steering linkage ball joint ball joint dust cover insecure so that it no longer prevents the ingress of dirt steering box drop arm (2.1.3 (g) (ii))

MAJOR Nearside Front Drag link end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice (0.1 (b))

Rear Registration plate deteriorated but not likely to be misread number plate has slight damage

MOT #10 2020-11-11 15:20

MOT test number 758188193633

Result ✓ Passed

Advice

Rear Registration plate deteriorated but not likely to be misread number plate has slight damage

(0.1 (b))

MOT #9 2019-11-13 16:21

MOT test number 370671474294

Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre worn on inner edge (5.2.3 (e))

Advice Nearside Front Track rod end ball joint has slight play as marked (2.1.3 (b) (i))

CarCheck.co.uk page 4/13



MOT #8 2018-11-22 10:08

MOT test number 579751514747

MOT #7 2017-11-02 13:07

MOT test number 253891530318

Result

Passed

MOT #6 2017-10-31 11:57

MOT test number 856103231212

Result X Failed

Fail Nearside Front Outer Drag link end ball joint has excessive play rear most as marked. (2.2.B.1f)

Fail Front Lower Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt steering box drop arm (2.2.C.1c)

Fail Nearside Fuel system component leaking fuel cooler as marked (7.2.3)

MOT #5 2016-11-15 16:06

MOT test number 912109134707

MOT #4 2015-11-19 16:36

MOT test number 488678399507

Result ✓ Passed

MOT #3 2014-11-25 15:55

MOT test number 767469024397

MOT #2 2013-12-09 16:36

MOT test number 256053043341

Result \rightarrow Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2012-12-21 10:35

MOT test number 798426352316

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Days left 248
MOT expiry date 6 February 2025
Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincore

CV09NYS

report date: 2024-03-29

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this LAND ROVER had different number plates.

ÜK NA

More info >

CarCheck.co.uk page 10/13



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-04
Last registration	2024-02-06
Complete history	See info



Registration #1	2009-03-04	7 mi
Registration #2	2012-12-21	31.991 mi
Registration #3	2013-12-09	39.636 mi
Registration #4	2014-11-25	43.719 mi
Registration #5	2015-11-19	47.887 mi
Registration #6	2016-11-15	51.732 mi
Registration #7	2017-10-31	55.810 mi
Registration #8	2017-11-02	55.815 mi
Registration #9	2018-11-22	58.092 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 12/13



		_		
- 11	manci	ODC X	. WA	iaht
וט	mensi	UHSC	\times \vee \vee \subset	ullu

Width	1790 mm
Height	1968 mm
Length	3649 mm
Kerb weight	1750 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Number of axles	2
Engine number	090224122932244DT

CarCheck.co.uk page 13/13