





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|------------------|
| Model | PULSAR N-TEC DCI |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 118 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 108 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 2.500 rpm |
| Engine capacity | 1.461 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 68.9 mpg |
| Consumption extra urban | 85.6 mpg |
| Consumption combined | 78.5 mpg |
| CO2 emission | 94 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/13




Internet history

Entry 1


Date 2021-07-24

Pictures 40

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2024-09-07 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 15 |
| Total items failed | 11 |

| MOT #11 | 2023-09-07 14:24 |
|---|-----------------------------|
| MOT test number | 901896077490 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-07 |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material (c)) | at flexi to caliper (1.1.11 |

| MOT #10 | 2023-09-05 10:03 |
|---|-----------------------------|
| MOT test number | 354459285290 |
| Result | × Failed |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material a | at flexi to caliper (1.1.11 |
| Minor Nearside Windscreen wiper blade defective smearing (3.4 (b) (i)) | |
| Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) | |
| Fail Offside Parking brake inoperative on one side (1.4.1 (a)) | |
| Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| Minor Offside Windscreen wiper blade defective smearing (3.4 (b) (i)) | |
| Fail Parking brake lever has excessive movement indicating incorrect adjustment | ent (1.1.6 (c)) |

CarCheck.co.uk page 3/13



MOT #9 2022-09-08 15:26

MOT test number 539177193232

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8 2022-09-07 11:44

MOT test number 503195390533

Result X Failed

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #7 2021-08-16 12:43

MOT test number 528197402622

CarCheck.co.uk page 4/13



MOT #6 2021-08-13 13:17

MOT test number 506107462683

Result X Failed

Fail Nearside Front Suspension arm ball joint excessively worn Excessive play n s f ball joint (5.3.4 (a) (i))

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #5 2020-08-20 14:53

MOT test number 849952633717

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4 2020-03-18 10:44

MOT test number 316842302285

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #3 2019-04-03 09:56

MOT test number 924656949091

Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

MOT #2 2018-04-02 10:01

MOT test number 398758145161

CarCheck.co.uk page 5/13



MOT #1 2018-01-31 11:24

MOT test number 832892125596

Result ✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/13



See MOT history

Tax & MOT check

Tax expired: 26 January 2024



MOT

Expires: 7 September 2024

Expired at 26 January 2024 **Tax status Days left** 94 days too late **MOT** expiry date 7 September 2024

Tax calculation

Full MOT history

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
|--|-------------|
| | |
| HARMAN CONTRACTOR CONT | |
| | |
| *************************************** | |
| ******* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | UK ZIS |
| Plate since | |
| | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2015-03-28 |
| Last registration | 2023-09-07 |
| Complete history | See info |



| Registration #1 | 2015-03-28 | 15 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-01-31 | 39.287 mi |
| Registration #3 | 2018-04-02 | 40.567 mi |
| Registration #4 | 2019-04-03 | 46.757 mi |
| Registration #5 | 2020-03-18 | 56.410 mi |
| Registration #6 | 2020-08-20 | 61.231 mi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 0.00 44 |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 70.777 au |

More info >

CarCheck.co.uk page 12/13



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 81% |
| Pedestrian | 75% |
| Safety systems | 68% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 2017 mm |
|---------------------|---------|
| Height | 1520 mm |
| Length | 4387 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1352 kg |
| Max. allowed weight | 1785 kg |

Additional information

| Fuel tank capacity | 46 I | |
|-----------------------------------|------------------|----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 pag | ge 13/13 |