





report date: 2024-03-29

General information

Make	RENAULT
Model	ZOE DYNAMIQUE INTENS
Colour	Grey
Year of manufacture	2015
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	87 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-25

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-22
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	26
Total items failed	0

MOT #8		2023-10-19 11:49
MOT test	number	167900317547
Result		✓ Passed
Next expi	ry date	2024-10-22
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Tpms light on	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



Advice

Tpms light on

UU11TAG
report date: 2024-03-29

MOT #7 2023-10-19 10:29

MOT test number 859676588822 Result **X** Failed **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **MAJOR** Nearside Rear Direction indicator incorrect colour white not orange (4.4.3 (a)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Offside Rear Direction indicator incorrect colour white not orange (4.4.3 (a)) Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6		2022-10-18 09:51
MOT test	number	522320826523
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2021-10-02 09:21
MOT test number	782174759402
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #4 2020-10-23 09:30

MOT test number 893040567866

MOT #3 2019-05-29 11:53

MOT test number 342446305250

Advice Offside Front tyre edges worn and perished

Advice Nearside Front tyre edges worn and perished

MOT #2 2018-05-31 14:41

MOT test number 634258273004

Result \rightarrow Passed

Advice Offside Front tyre cracked outer edge

MOT #1 2018-03-22 11:42

MOT test number 313571707978

Result ✓ Passed

Advice Covers fitted to the vehicle preventing the inspection of some components

CarCheck.co.uk page 5/12



Tax & MOT check



MOT expiry date 154

MOT expiry date 22 October 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	ZIE UK
Plate since	
Current registration	OK ON THE OWNER OF THE OWNER OWN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-23
Last registration	2023-10-19
Complete history	See info



Registration #1	2015-03-23	29 mi
Registration #2	2018-03-22	3.472 mi
Registration #3	2018-05-31	3.651 mi
Registration #4	2019-05-29	4.445 mi
Registration #5	2020-10-23	5.534 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1943 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 12/12