



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	2007
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-11-18
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-01-22
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	43
Total items failed	6

MOT #17 2023-01-23 12:09

MOT test number 246242691842

Result ✓ Passed

Next expiry date 2024-01-22

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

MOT #16 2021-11-25 11:57

MOT test number 216632177542

Result ✓ Passed

- Advice** Suspension component mounting prescribed area damaged but not considered excessive sills and suspension mounts (5.3.6 (a) (i))

**MOT #15**

2021-11-15 11:41

MOT test number

272737144546

Result

✓ Passed

Advice Front front sub frame corroded**Advice** Rear both rear springs corroded**Advice** Windscreen chip in zone a**MOT #14**

2020-11-04 13:59

MOT test number

533818315832

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front tyres worn heavily on inner edges**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**MOT #13**

2020-05-15 13:29

MOT test number

313218277383

Result

✗ Failed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Advice** Nearside Front Nail in tyre**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Power steering malfunctioning (2.1.5 (a))

**MOT #12** 2019-05-13 11:20**MOT test number** 541613097143**Result** ✓ Passed**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Centre stop lamp not working**MOT #11** 2018-05-17 10:30**MOT test number** 353390378386**Result** ✓ Passed**MOT #10** 2017-05-19 08:12**MOT test number** 485168837064**Result** ✓ Passed**MOT #9** 2016-09-16 14:01**MOT test number** 629628868533**Result** ✓ Passed**MOT #8** 2015-09-17 11:20**MOT test number** 295690992292**Result** ✓ Passed**MOT #7** 2014-09-17 11:56**MOT test number** 187900164217**Result** ✓ Passed**Advice** Steering system slightly tight (2.2.D.1)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6**

2013-09-19 14:20

MOT test number

397062163236

Result

✗ Failed

Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Slight play in offside steering rack ball end**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Both front brake discs wearing on inner surfaces**MOT #5**

2013-09-19 14:20

MOT test number

317182163280

Result

✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Slight play in offside steering rack ball end**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Both front brake discs wearing on inner surfaces**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4**

2012-09-14 10:58

MOT test number

156418352225

Result

✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Both front brake discs worn on inner surfaces

**MOT #3** 2012-09-13 11:51**MOT test number** 429847152222**Result** ✗ Failed**Notice** Both front brake discs worn on inner surfaces**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2011-09-14 15:17**MOT test number** 326517551423**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #1** 2010-09-17 14:23**MOT test number** 382330660269**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2024

X

MOT

Expired:
22 January 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	22 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-18
Last registration	2023-01-23
Complete history	See info



Registration #1	2007-09-18	15 mi
Registration #2	2010-09-17	30.995 mi
Registration #3	2011-09-14	40.220 mi
Registration #4	2012-09-13	48.530 mi
Registration #5	2012-09-14	48.530 mi
Registration #6	2013-09-19	56.885 mi
Registration #7	2014-09-17	65.227 mi
Registration #8	2015-09-17	69.460 mi
Registration #9	2016-09-16	74.243 mi
Registration #10	2017-09-16	75.277 mi
Registration #11	2018-09-16	75.277 mi
Registration #12	2019-09-16	75.277 mi
Registration #13	2020-09-16	75.277 mi
Registration #14	2021-09-16	75.277 mi
Registration #15	2022-09-16	75.277 mi
Registration #16	2023-01-23	75.277 mi
Registration #17	2023-01-23	75.277 mi
Registration #18	2023-01-23	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	6G84817
---------------	---------