



report date: 2024-03-28

General information

Make	VAUXHALL
Model	CORSA SRI VX-LINE NAV BLACK
Colour	Grey
Year of manufacture	2018
Top speed	109 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	43.5 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-03-09
Pictures	9
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2025-03-23
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #7 2024-03-22 16:17**MOT test number** 274905834259**Result** ✓ Passed**Next expiry date** 2025-03-23

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2024-03-22 14:38**MOT test number** 132197528730**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Windscreen washer not working (3.5 (a))

**MOT #5** 2023-03-24 16:36**MOT test number** 727001723775**Result** ✓ Passed

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #4 2023-03-24 10:46**MOT test number** 559059894541**Result** ✗ Failed

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #3 2022-03-21 17:27**MOT test number** 733126843995**Result** ✓ Passed**MOT #2** 2022-03-21 10:27**MOT test number** 279021848849**Result** ✗ Failed

Fail Rear Reversing lamp inoperative (4.6.1 (a))

MOT #1 2021-03-18 17:56**MOT test number** 333691089851**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SK68YGN
Plate since	2019-09-29
Current registration	 SK68YGN
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-09-25
Last registration	2024-03-22
Complete history	See info




Registration #1	2018-09-25	15 mi
Registration #2	2019-03-20	25,277 mi
Registration #3	2021-03-18	11.831 mi
Registration #4	2022-03-21	16.779 mi
Registration #5	2022-03-21	16.779 mi
Registration #6	2023-03-20	25,277 mi
Registration #7	2023-03-20	25,277 mi
Registration #8	2023-03-20	25,277 mi
Registration #9	2024-03-22	25,277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	77%
Pedestrian	71%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1746 mm
Height	1481 mm
Length	4021 mm
Wheel base	2510 mm
Kerb weight	1088 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19TW5771LDD