





report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH M 1000 ENTERPRISE BLUEHDI S/S
Colour	White
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/11



NK18XOV report date: 2024-03-28

Internet history

Entry 3

Date 2021-10-12

Pictures 0

Listing price <u>View report</u>

source: heycar.co.uk

Entry 2

Date 2021-08-11

Pictures 35

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date	2021-07-30

Pictures 1

Listing price <u>View report</u>



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-09-29
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #6		2023-09-27 12:24
MOT test	number	937728388562
Result		✓ Passed
Next expi	ry date	2024-09-29
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Windscreen has a chip	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #5	2022-09-26 14:17
MOT test number	487349148293
Result	✓ Passed
MOT #4	2022-09-26 14:17
MOT test number	2022-09-26 14:17 978834199338

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

177573388658

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged Slightly out out shape (5.2.3 (d) (ii))

MOT #2 2021-09-21 13:49 **MOT** test number 829028293317 Result **X** Failed **MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) **MAJOR** Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre slightly damaged Slightly out out shape (5.2.3 (d) (ii))

MOT #1	2021-03-30 08:19
MOT test number	167179359914
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expires: 29 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



NK18XOV report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

manus .	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



NK18XOV report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-03-31
Last registration	2023-09-27
Complete history	See info



2018-03-31	22 mi
2021-03-30	44.786 mi
	9.79 66
	0.77 66
2021-09-21	47.486 mi
	11.777 es
	11.777 ea 11.777 ea
	0.00 m 0.00 m 0.00 m
	11.777 es 11.777 es 11.777 es
	2021-03-30

More info >

CarCheck.co.uk page 10/11



NK18XOV report date: 2024-03-28

Dimensions & weight

Width	2204 mm
Height	1899 mm
Length	4959 mm
Kerb weight	1533 kg
Max. allowed weight	2660 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	3
Engine number	JCAP0004806

CarCheck.co.uk page 11/11