



NJ55YHS

report date: 2024-03-28

General information

Make	AUDI
Model	A6 TDI S LINE
Colour	Black
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg



LABEL UNKNOWN

**MOT history**

MOT #19	2022-05-30 11:01
MOT test number	931387505119
Result	✓ Passed
Next expiry date	2023-05-29
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre slightly damaged/cracking or perishing slight cracking on inner sidewall (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing slight cracking on inner sidewall (5.2.3 (d) (ii))
Minor	Offside Front Headlamp lens slightly defective lens deteriorated (4.1.1 (b) (i))
Advice	Nearside Front Headlamp has a product on the light source but not seriously reducing light output lens deteriorated (4.1.4 (b))

MOT #18	2021-03-24 14:05
MOT test number	783908580547
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-03-24 12:11
MOT test number	312823280692
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #16** 2020-02-14 12:32**MOT test number** 745856335060**Result** ✓ Passed**Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15** 2020-02-14 11:25**MOT test number** 791631509939**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #14** 2019-02-19 12:41**MOT test number** 631895084989**Result** ✓ Passed**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Items removed from driver's view prior to test

**MOT #13** 2019-02-18 12:22**MOT test number** 463613386882**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #12** 2018-02-02 11:52**MOT test number** 816530717581**Result** ✓ Passed**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #11** 2017-01-09 17:05**MOT test number** 928345208506**Result** ✓ Passed**MOT #10** 2017-01-09 11:55**MOT test number** 148901741984**Result** ✗ Failed**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #9** 2016-01-19 13:07**MOT test number** 345710062855**Result** ✓ Passed

- Advice** N/S/F Tyre tread worn on inner edge
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Under trays fitted obscuring some underside components
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Engine covers fitted obscuring some under bonnet components
- Advice** Nearside Front Tyre worn close to the legal limit 2mm left (4.1.E.1)

MOT #8 2015-02-06 10:03**MOT test number** 107247135040**Result** ✓ Passed**MOT #7** 2014-01-10 10:04**MOT test number** 439920114025**Result** ✓ Passed**MOT #6** 2012-07-04 14:03**MOT test number** 868246482121**Result** ✓ Passed

**MOT #5**

2012-07-03 11:43

MOT test number

695135682139

Result**✗ Failed**

- Fail** Offside Headlamp aim too low (1.8)
- Fail** Nearside Front Upper Front suspension has serious deterioration of the bonding between metal and flexible material of an upper support bearing (2.5.B.3a)
- Fail** Offside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Brake warning device not working correctly (3.3.D.3a)
- Fail** Nearside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #4

2011-06-30 10:43

MOT test number

817941381105

Result**✓ Passed**

- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #3

2010-06-29 13:52

MOT test number

390600180153

Result**✓ Passed****MOT #2**

2009-06-29 15:09

MOT test number

531790389102

Result**✓ Passed**

- Advice** Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2008-06-30 16:44
MOT test number	263992688140
Result	✓ Passed



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-20
Current registration	
Plate since	2019-06-20

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-01
Last registration	2022-05-30
Complete history	See info



Registration #1	2005-09-01	19 mi
Registration #2	2008-06-30	35.070 mi
Registration #3	2009-06-29	45.446 mi
Registration #4	2010-06-29	53.157 mi
Registration #5	2011-06-30	61.153 mi
Registration #6	2012-07-03	72.096 mi
Registration #7	2012-07-04	72.096 mi
Registration #8	2014-01-10	79.820 mi
Registration #9	2015-02-06	85.181 mi
Registration #10	2016-01-19	91.116 mi
Registration #11	2016-01-19	91.116 mi
Registration #12	2016-01-19	91.116 mi
Registration #13	2016-01-19	91.116 mi
Registration #14	2016-01-19	91.116 mi
Registration #15	2016-01-19	91.116 mi
Registration #16	2016-01-19	91.116 mi
Registration #17	2016-01-19	91.116 mi
Registration #18	2016-01-19	91.116 mi
Registration #19	2016-01-19	91.116 mi
Registration #20	2016-01-19	91.116 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2843 mm
Kerb weight	1610 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BLB 121820