



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA
Colour	Red
Year of manufacture	2007
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg
CO2 emission	197 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-11-13
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-11-16
<b>MOT pass rate</b>	88 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	41
<b>Total items failed</b>	4

**MOT #17** 2023-11-17 16:37**MOT test number** 444973225314**Result** ✓ Passed**Next expiry date** 2024-11-16

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill corroded (5.3.6 (a) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill corroded (5.3.6 (a) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16** 2022-11-11 08:35**MOT test number** 552913825840**Result** ✓ Passed

- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15** 2021-11-15 11:56**MOT test number** 608932581956**Result** ✓ Passed**MOT #14** 2021-06-11 15:12**MOT test number** 816162985752**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** General underbody corrosion
- Advice** Offside rear trailing arm bush worn but not resulting in excessive movement
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside wiper arm loose
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside rear trailing arm bush worn but not resulting in excessive movement
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Side repeater insecure (4.4.1 (c) (i))

**MOT #13** 2020-02-12 14:31**MOT test number** 258735766405**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-02-07 15:40**MOT test number** 483284214727**Result** ✓ Passed**MOT #11** 2018-02-06 10:49**MOT test number** 312487220614**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit tyre on wear bars (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit tyre on wear bars (4.1.E.1)
- Advice** Central Rear exhaust rear box support broken /supported by wire now
- Advice** Nearside Rear Tyre worn close to the legal limit tyre close to wear bars (4.1.E.1)

**MOT #10** 2017-02-08 10:09**MOT test number** 895058775437**Result** ✓ Passed

- Advice** Exhaust hangers badly corroded middle section
- Advice** Engine covers fitted
- Advice** Front brake pads getting low
- Advice** Childrens seats fitted
- Advice** Nearside Rear passenger door damage



<b>MOT #9</b>	2017-02-06 13:21
<b>MOT test number</b>	590590373605
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Side repeater excessively damaged so that it is not visible from a reasonable distance mirror casing is damage (1.4.A.2e)
<b>Advice</b>	Childrens seats fitted
<b>Advice</b>	Nearside Rear passenger door damage
<b>Advice</b>	Exhaust hangers badly corroded middle section
<b>Fail</b>	Offside Front Front position lamp(s) not working (1.1.A.3b)
<b>Advice</b>	Engine covers fitted
<b>Advice</b>	Front brake pads getting low

<b>MOT #8</b>	2016-02-17 17:17
<b>MOT test number</b>	827715196848
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2015-06-22 12:56
<b>MOT test number</b>	109493875161
<b>Result</b>	✓ Passed
<b>Notice</b>	Front tyres 3mm tread depth.rear silencer hanger heavily corroded.

<b>MOT #6</b>	2014-06-05 10:04
<b>MOT test number</b>	668546054181
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2013-06-20 15:45
<b>MOT test number</b>	299061873119
<b>Result</b>	✓ Passed

**MOT #4** 2013-06-17 15:39**MOT test number** 889728963187**Result** ✗ Failed**Fail** Nearside Rear Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**MOT #3** 2012-06-08 10:58**MOT test number** 989480562171**Result** ✓ Passed**MOT #2** 2011-06-03 09:38**MOT test number** 719484651102**Result** ✓ Passed**MOT #1** 2010-06-10 14:58**MOT test number** 281411960125**Result** ✓ Passed**Notice** Air bag warning light illuminated



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
16 November 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	16 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-07-30
Last registration	2023-11-17
Complete history	<a href="#">See info</a>



Registration #1	2007-07-30	19 mi
Registration #2	2010-06-10	10.143 mi
Registration #3	2011-06-03	18.087 mi
Registration #4	2012-06-08	24.070 mi
Registration #5	2013-06-17	29.523 mi
Registration #6	2013-06-20	29.523 mi
Registration #7	2014-06-05	34.759 mi
Registration #8	2015-06-22	39.272 mi
Registration #9	2016-02-17	41.994 mi
Registration #10	2017-02-06	49.152 mi
Registration #11	2018-06-20	49.152 mi
Registration #12	2019-06-20	49.152 mi
Registration #13	2020-06-20	49.152 mi
Registration #14	2021-06-20	49.152 mi
Registration #15	2022-06-20	49.152 mi
Registration #16	2023-06-20	49.152 mi
Registration #17	2024-06-20	49.152 mi
Registration #18	2025-06-20	49.152 mi
Registration #19	2026-06-20	49.152 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1829 kg
Max. allowed weight	2415 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	7Y20215