



SEAT

 **KPI3BWN**


report date: 2025-02-13

General information

Make	SEAT
Model	IBIZA ECOMOTIVE TDI CR ECOMOTIVE SE
Colour	Red
Year of manufacture	2013
Top speed	107 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	91.1 mpg
Consumption combined	80.7 mpg
CO2 emission	92 g/km
CO2 label	A






Internet history

Entry 1

Date	2023-01-22
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-09-10
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	36
Total items failed	4

MOT #13 2024-09-11 15:53

MOT test number 720772345012

Result ✔ Passed

Next expiry date 2025-09-10

Minor Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Coolant low



MOT #12 2024-09-11 12:07

MOT test number 610374655366

Result ✗ Failed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Pass with rectification** Windscreen washer provides insufficient washer liquid both (3.5 (a))
- Advice** Coolant low
- Minor** Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2024-01-17 14:18

MOT test number 812733441502

Result ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #10 2024-01-10 12:27

MOT test number 902140350004

Result ✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction eml on (8.2.2.2 (g))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2023-01-17 10:48

MOT test number 279873873671

Result ✓ Passed

- Advice** Emissions to low to register
- Advice** Exhaust corroded

MOT #8 2022-06-18 10:03

MOT test number 503202577302

Result ✓ Passed

- Advice** Emissions to low to register

MOT #7 2021-06-21 08:12

MOT test number 213902869390

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Emissions to low to register
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #6	2021-06-14 09:00
MOT test number	610600145474
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Emissions too low to register
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5	2020-07-01 15:47
MOT test number	947258135240
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4	2019-09-26 14:17
MOT test number	779765858910
Result	✓ Passed

MOT #3	2018-09-18 16:17
MOT test number	162431473373
Result	✓ Passed

MOT #2	2017-04-24 14:05
MOT test number	634706073419
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside front tyre wearing on inner edge
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1 2016-04-15 09:07

MOT test number 428713347276

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed

Tax due:
1 March 2026

✓
MOT

Expires:
10 September 2025

Tax status Valid until 1 March

Days left 349

MOT expiry date 10 September 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this SEAT. See if, where and when this SEAT had damage and the car repair costs. We also check if this SEAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SEAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SEAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this SEAT? How many owners did this SEAT have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT
SEAT	SEAT

More info >

Plate changes

See in this check if this SEAT had different number plates.

Number of plates	1
Current registration	SEAT
Plate since	2025-02-13
Current registration	SEAT
Plate since	2025-02-13

More info >



Finance check

Check if this SEAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SEAT has been settled.

If not, and you buy this SEAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SEAT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-04-10
Last registration	2024-09-11
Complete history	See info



Registration #1	2013-04-10	12 mi
Registration #2	2016-04-15	47.994 mi
Registration #3	2017-04-24	58.337 mi
Registration #4	2018-09-18	68.945 mi
Registration #5	2019-09-26	75.792 mi
Registration #6	2020-07-01	78.240 mi
Registration #7	2021-06-14	83.993 mi
Registration #8	2021-06-21	84.006 mi
Registration #9	2022-06-21	84.006 mi
Registration #10	2022-06-21	84.006 mi
Registration #11	2022-06-21	84.006 mi
Registration #12	2022-06-21	84.006 mi
Registration #13	2022-06-21	84.006 mi
Registration #14	2022-06-21	84.006 mi
Registration #15	2024-09-11	84.006 mi

[More info >](#)



Car features

The SEAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete SEAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	77%
Pedestrian	59%
Safety systems	71%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1693 mm
Height	1445 mm
Length	4061 mm
Wheel base	2469 mm
Kerb weight	1075 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CFW 414853