



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA EXPRESSION 16V
Colour	Silver
Year of manufacture	2006
Top speed	124 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	135 BHP
Max. torque	191 Nm at 3.750 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	32.5 mpg
CO2 emission	206 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-06-12
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-12
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	46
Total items failed	19

MOT #24	2023-06-07 17:23
MOT test number	569653552396
Result	✓ Passed
Next expiry date	2024-06-12
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #23	2022-06-13 09:34
MOT test number	230336538047
Result	✓ Passed

**MOT #22**

2022-05-26 11:20

MOT test number

541787250315

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Rear Tyre slightly damaged/cracking or perishing both rears (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner edges corroded and pitted (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Nail in tyre
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #21

2021-06-04 08:12

MOT test number

553107644601

Result

✓ Passed

MOT #20

2021-06-02 12:06

MOT test number

688208882329

Result

✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Engine MIL inoperative or indicates a malfunction eml light on (8.2.1.2 (h))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm tyre worn and ((at risk from offside front coil spring)) (5.2.3 (e))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #19** 2020-06-08 12:35**MOT test number** 560133508449**Result** ✓ Passed**MOT #18** 2020-06-05 08:58**MOT test number** 290916173590**Result** ✗ Failed

Fail Nearside Headlamp aim projected beam image is obviously incorrect bulb incorrectly fitted and lens oxyedised (4.1.2 (c))

Fail Engine MIL inoperative or indicates a malfunction eml light on (8.2.1.2 (h))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #17 2019-06-07 09:50**MOT test number** 300633574850**Result** ✓ Passed**MOT #16** 2019-06-03 14:05**MOT test number** 255565330475**Result** ✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt BOOT SPLIT LEAKING GREASE (6.1.7 (g) (ii))

Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

MOT #15 2018-06-07 10:47**MOT test number** 563954234850**Result** ✓ Passed

**MOT #14**

2018-06-06 14:22

MOT test number

913486508994

Result

✗ Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Steering rack has slight free play detected at steering wheel signs of slight wear to rack inner joint (2.3 (a) (i))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #13**

2017-05-23 14:17

MOT test number

445865290070

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit SHOWING WEAR TO EDGE (4.1.E.1)**Advice** Nearside Front COIL SPRING SHOWING WEAR**Advice** STEERING RACK SHOWING SLIGHT WEAR TO INNER JOINT NEAR SIDE**MOT #12**

2016-06-10 09:09

MOT test number

704918959590

Result

✓ Passed

MOT #11

2016-02-17 14:29

MOT test number

420002156215

Result

✓ Passed

Advice Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #10**

2016-02-17 08:53

MOT test number

502450121134

Result**✗ Failed****Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9**

2015-02-25 11:44

MOT test number

159776655494

Result**✓ Passed****Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**MOT #8**

2015-02-25 10:02

MOT test number

876546055080

Result**✗ Failed****Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)

**MOT #7** 2014-02-21 10:23**MOT test number** 139412154486**Result** ✓ Passed

- Advice** Nearside Outer Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear wheel bearing has slight play (2.6.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Outer Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2012-10-16 13:09**MOT test number** 305310592279**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2012-10-12 13:03**MOT test number** 556356082240**Result** ✗ Failed

- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2011-10-17 18:09**MOT test number** 355390791433**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-10-17 10:42**MOT test number** 169310991245**Result** ✗ Failed**Notice** Service due**Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-09-16 13:09**MOT test number** 771129350258**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Puncture nsf**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-09-16 13:38**MOT test number** 822349159269**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-10-25
Last registration	2023-06-07
Complete history	See info



Registration #1	2006-10-25	23 mi
Registration #2	2009-09-16	24.324 mi
Registration #3	2010-09-16	30.050 mi
Registration #4	2011-10-17	40.022 mi
Registration #5	2011-10-17	40.022 mi
Registration #6	2012-10-12	48.068 mi
Registration #7	2012-10-16	48.068 mi
Registration #8	2014-02-21	58.279 mi
Registration #9	2015-02-25	61.315 mi
Registration #10	2015-02-25	61.315 mi
Registration #11	2016-02-17	63.769 mi
Registration #12	2016-02-17	63.769 mi
Registration #13	2016-06-10	64.468 mi
Registration #14	2016-06-10	64.468 mi
Registration #15	2016-06-10	64.468 mi
Registration #16	2016-06-10	64.468 mi
Registration #17	2016-06-10	64.468 mi
Registration #18	2016-06-10	64.468 mi
Registration #19	2016-06-10	64.468 mi
Registration #20	2016-06-10	64.468 mi
Registration #21	2016-06-10	64.468 mi
Registration #22	2016-06-10	64.468 mi
Registration #23	2016-06-10	64.468 mi
Registration #24	2016-06-10	64.468 mi
Registration #25	2016-06-10	64.468 mi
Registration #26	2016-06-10	64.468 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1475 mm
Length	4713 mm
Wheel base	2748 mm
Kerb weight	1350 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	C004354