



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D SE LUX
Colour	Black
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G








Internet history

Entry 2

Date	2021-12-18
Pictures	43
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-10
Pictures	35
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-24
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	34
Total items failed	7

MOT #18	2024-02-05 16:32
MOT test number	375023867027
Result	✓ Passed
Next expiry date	2025-02-24

MOT #17	2024-01-29 13:45
MOT test number	748543992445
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Fail	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))

MOT #16	2023-02-06 14:04
MOT test number	110363845753
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2022-01-25 11:29
MOT test number	721444680246
Result	✓ Passed

**MOT #14**

2022-01-24 14:19

MOT test number

800504847839

Result

✗ Failed

Fail

Nearside Headlamp light intensity severely reduced (4.1.4 (a))

MOT #13

2021-02-10 15:43

MOT test number

695637062828

Result

✓ Passed

Advice

Front BOTH FRONT TYRES STARTING TO WEAR ON EDGES.

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play REPLACE SOON. (5.3.4 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT BRAKE DISCS HEAVILY WORN ,LIPPED & CORRODED,ADVISE REPLACE A.S.A.P. (1.1.14 (a) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Nearside Front NSF BRAKE BACK PLATE DAMAGED,LOOSE,RUSTY & CATCHING ON BRAKE DISCS,ADVISE REPLACE.

Advice

Rear Exhaust mounting defective LAST BUT ONE EXHAUST HANGER GETTING READ TO SNAP OFF,ADVISE WELD BACK ON . (6.1.2 (a))

Advice

HAND BRAKE REQUIRES AJUSTMENT.

Advice

Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords NSR TYRE HAS CUT ON INNER SHOULDER CLOSE TO CORDS,ADVISE REPLACE SOON. (5.2.3 (d) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened REAR BRAKE DISCS CORRODED ON OUTER EDGES. (1.1.14 (a) (ii))

Advice

Front FRONT INNER BRAKE PADS NOT VISIBLE WITH WHEELS ON.

Advice

Rear Exhaust mounting defective REAR SECTION EXHAUST HANGER RUSTED OFF,ADVISE WELD BACK ON. (6.1.2 (a))

**MOT #12** 2020-02-13 12:51**MOT test number** 648142277261**Result** ✓ Passed**Advice** BOOK TIME FOR SERVICE ON DASH.**Advice** CAM BELT HISTORY?**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened FRONT BRAKE DISCS LIPPED & WORN. (1.1.14 (a) (ii))**Advice** UNDER BODY COVERS OBSCURING SOME TESTABLE ITEMS.**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH FRONT BOTTOM ARM REAR BUSHES HAVE SOME MOVEMENT, REPLACE SOON. (5.3.4 (a) (i))**MOT #11** 2019-02-25 14:17**MOT test number** 319123670158**Result** ✓ Passed**MOT #10** 2018-02-20 14:25**MOT test number** 847952814484**Result** ✓ Passed**MOT #9** 2018-02-20 09:47**MOT test number** 631950301349**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #8** 2017-02-01 11:45**MOT test number** 795906547862**Result** ✓ Passed



MOT #7	2017-02-01 10:38
MOT test number	633707760108
Result	✗ Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)

MOT #6	2016-01-20 11:04
MOT test number	904985534386
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	TYRE SIZE: 235/40X18 91Y

MOT #5	2016-01-18 09:49
MOT test number	720527757406
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	TYRE SIZE: 235/40X18 91Y
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #4** 2015-01-21 17:08**MOT test number** 339911925042**Result** ✓ Passed

- Notice** O/s/f tyre worn close to legal minimum
- Notice** O/s/f wheel rim slightly buckled
- Notice** Front brake pads worn thin
- Notice** N/s/f tyre worn heavily on inner edge and close to legal minimum

MOT #3 2014-01-07 10:04**MOT test number** 807267704076**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2 2013-01-12 12:08**MOT test number** 547872913073**Result** ✓ Passed**MOT #1** 2013-01-12 12:08**MOT test number** 166142513045**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
24 February 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY59LEF
Plate since	2019-03-29
Current registration	YY59LEF
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-12
Last registration	2024-02-05
Complete history	See info



Registration #1	2010-01-12	14 mi
Registration #2	2013-01-12	42.695 mi
Registration #3	2014-01-07	52.781 mi
Registration #4	2015-01-21	58.061 mi
Registration #5	2016-01-18	62.091 mi
Registration #6	2016-01-20	62.123 mi
Registration #7	2017-02-01	67.146 mi
Registration #8	2017-02-01	67.146 mi
Registration #9	2018-02-20	73.453 mi
Registration #10	2018-02-20	73.453 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1743 kg
Max. allowed weight	2090 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number	711961
---------------	--------