





report date: 2024-03-28

General information

Make	ТОУОТА
Model	COROLLA D-4D T3
Colour	Silver
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	279 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-14
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	15
Total items failed	8

MOT #15	2024-04-15 10:47
MOT test number	632289058654
Result	✓ Passed
Next expiry date	2025-04-14

MOT #14	2022-12-13 12:36
MOT test number	191594908158
Result	✓ Passed

MOT #13	2022-01-13 12:04
MOT test number	620820541824
Result	✓ Passed

MOT #12		2022-01-13 12:04
MOT test number		428641596012
Result		X Failed
Pass with rectification	Windscreen washer not working (3.5 (a))	

MOT #11	2017-10-26 14:30
MOT test number	432911067995
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #10 2017-10-13 13:41

MOT test number 824128209813

Result X Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9 2015-03-25 11:44

MOT test number 965344385058

Result \(\sqrt{Passed} \)

MOT #8 2015-03-19 11:49

MOT test number 146958475018

Result X Failed

Notice O/s washer jets misaimed

Fail Nearside Headlamp insecure (1.7.3)

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Front front brake application uneven (3.7.B.2)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #7 2014-03-24 09:26

MOT test number 285013684096

Result ✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Notice Slight binding at nearside front wheel not showing in rolling brake tester

Advice Front registration plate faded but not likely to be misread (6.3.1d)

CarCheck.co.uk page 4/13



✓ Passed

MOT #6 2014-03-24 09:26

MOT test number 965203784039

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Front registration plate faded but not likely to be misread (6.3.1d)

Advice Parking brake lever has little reserve travel (3.1.6b)

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Notice Slight binding at nearside front wheel not showing in rolling brake tester

MOT #5 2013-03-25 13:07

MOT test number 745474283055

Notice Front wipers poor just clearing view

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Advice Parking brake lever has little reserve travel (3.1.6b)

Notice Nail in offside rear tyre

Result

Notice Engine covers fitted obscuring some components in the engine bay

MOT #4 2011-12-28 10:49

MOT test number 135492061311

Result ✓ Passed

MOT #3 2010-08-25 10:48

MOT test number 251587330200

Result

✓ Passed

CarCheck.co.uk page 5/13



MOT #2	2009-05-27 11:27
MOT test number	660057549147
Result	✓ Passed
MOT #1	2008-05-27 16:34
MOT test number	844908948116
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
manus .	

manus .	

	More info >
Plate changes	
Coo in this chook if this TOYOTA had different much on plates	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK ME
Fiate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2005-04-12
Last registration	2024-04-15
Complete history	See info



Registration #1	2005-04-12	28 mi
Registration #2	2008-05-27	50.926 mi
Registration #3	2009-05-27	59.143 mi
Registration #4	2010-08-25	68.759 mi
Registration #5	2011-12-28	78.202 mi
Registration #6	2013-03-25	86.970 mi
Registration #7	2014-03-24	92.863 mi
Registration #8	2015-03-19	98.754 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		D.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

77,777 86

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1300 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	55	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	2 13/13

Number of axles 2

Engine number 1CDU118799