



UK **YT58SYF**


General information

report date: 2022-07-05

Make	ABARTH
Model	GRANDE PUNTO 155 BHP ABARTH
Colour	Black
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.5 mpg
Consumption extra urban	44.4 mpg
Consumption combined	34.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Advert 1

Date	2021-08-20
Pictures	4
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2022-11-28
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #13	2021-11-29 16:52
MOT test number	963372596877
Result	✓ Passed
Next expiry date	2022-11-28

MOT #12	2021-11-25 16:32
MOT test number	314134117863
Result	✗ Failed
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Windscreen washer not working (3.5 (a))

MOT #11	2020-08-05 08:50
MOT test number	450226976896
Result	✓ Passed
Advice	General corrosion to suspension components



MOT #10 2019-08-13 10:05

MOT test number 182031323971

Result ✓ Passed

- Advice** Undertrays fitted not allowing full inspection
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2018-08-13 13:15

MOT test number 111436321682

Result ✓ Passed

- Advice** Under trays fitted not allowing full inspection of under carriage
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-08-13 10:37

MOT test number 315694829890

Result ✗ Failed

- Advice** Under trays fitted not allowing full inspection of under carriage
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Upper Macpherson strut pin or bush excessively worn strut top mount (5.3.4 (a) (i))

MOT #7 2017-08-15 11:15

MOT test number 181884374080

Result ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #6 2016-09-26 12:06

MOT test number 690359458122

Result ✓ Passed

MOT #5 2015-09-26 09:39

MOT test number 535004102132

Result ✓ Passed

MOT #4 2014-09-12 14:17

MOT test number 598025854284

Result ✓ Passed

MOT #3 2013-09-13 11:19

MOT test number 999546853268

Result ✓ Passed

MOT #2 2012-09-18 15:55

MOT test number 706272762250

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2011-09-03 11:01

MOT test number 846156541262

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Notice Child seat fitted not allowing full inspection of adult belt

Notice Undertray fitted unable to carry out full inspection



Tax & MOT check

×
Untaxed
Tax expired:
9 Juli 2021

✓
MOT
Expires:
28 November 2022

Tax status	Expired at 9 Juli 2021
Days left	401 days too late
MOT expiry date	28 November 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 210,00,-
Single six month payment	£ 110,25,-
Total payable by 12 monthly instalments	£ 220,50,-




Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

Download >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

Download >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

Download >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

Download >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

Download >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-09-05
Last registration	2021-11-29
Complete history	See info



Registration #1	2008-09-05	14 mi
Registration #2	2011-09-03	25.541 mi
Registration #3	2012-09-18	39.045 mi
Registration #4	2013-09-13	48.567 mi
Registration #5	2014-09-12	60.454 mi
Registration #6	2015-09-26	69.674 mi
Registration #7	2016-09-26	79.455 mi
Registration #8	2017-08-15	83.992 mi
Registration #9	2018-08-15	88.533 mi
Registration #10	2019-08-15	93.074 mi
Registration #11	2020-08-15	97.615 mi
Registration #12	2021-08-15	102.156 mi
Registration #13	2021-11-29	106.697 mi
Registration #14	2021-11-29	106.697 mi
Registration #15	2021-11-29	106.697 mi

[Download >](#)



Premium report

Get the ABARTH premium report and get full access to more information.

- ✓ Finance check
- ✓ Mileage registrations (15)
- ✓ Damage check
- ✓ Stolen check
- ✓ Car features list
- ✓ Owners history + plate changes

[Download >](#)

Dimensions & weight

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine code	1308914