



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Red
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-23
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-14
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	25
Total items failed	11

MOT #18	2023-12-06 14:09
MOT test number	694466296200
Result	✓ Passed
Next expiry date	2024-12-14
Advice	Service brake fluctuating, but not excessively o/s front (1.2.1 (e))
Advice	Service brake fluctuating, but not excessively n/s front (1.2.1 (e))

MOT #17	2023-12-06 09:27
MOT test number	186482782754
Result	✗ Failed
Fail	Tyre has ply or cords exposed o/s front inner edge (5.2.3 (d) (ii))
Advice	Service brake fluctuating, but not excessively o/s front (1.2.1 (e))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Service brake fluctuating, but not excessively n/s front (1.2.1 (e))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Position lamp not working n/s front (4.2.1 (a) (ii))



<b>MOT #16</b>	2022-12-15 16:25
<b>MOT test number</b>	240432639643
<b>Result</b>	✓ Passed
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #15</b>	2021-10-28 15:58
<b>MOT test number</b>	807996223213
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2021-10-25 09:25
<b>MOT test number</b>	974992734103
<b>Result</b>	✗ Failed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Offside Rear Service brake binding but not excessively (1.2.1 (f))
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Headlamp aim too far to the right (4.1.2 (a))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
<b>Fail</b>	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Exhaust hanger broken off at front

**MOT #13**

2021-06-21 11:05

**MOT test number**

961163115834

**Result**

✓ Passed

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #12**

2021-06-18 09:59

**MOT test number**

299877119159

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #11**

2019-07-24 12:20

**MOT test number**

880150829984

**Result**

✓ Passed

**MOT #10**

2018-07-26 15:37

**MOT test number**

380857062984

**Result**

✓ Passed

**MOT #9** 2018-02-15 09:21**MOT test number** 401779726045**Result** ✓ Passed**MOT #8** 2017-02-20 09:17**MOT test number** 112131721151**Result** ✓ Passed**MOT #7** 2016-02-12 16:32**MOT test number** 687272902504**Result** ✓ Passed**MOT #6** 2016-02-12 16:32**MOT test number** 981870515879**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2015-04-28 10:05**MOT test number** 246948115437**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2015-04-28 10:05**MOT test number** 938638515109**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #3	2014-04-30 09:45
MOT test number	647230724142
Result	✓ Passed

MOT #2	2014-04-30 09:45
MOT test number	109030324187
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #1	2013-04-30 15:52
MOT test number	457000423188
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
14 December 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	14 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-06
Last registration	2023-12-06
Complete history	<a href="#">See info</a>



Registration #1	2010-05-06	23 mi
Registration #2	2013-04-30	20.755 mi
Registration #3	2014-04-30	31.094 mi
Registration #4	2015-04-28	42.429 mi
Registration #5	2016-02-12	50.297 mi
Registration #6	2016-02-12	50.297 mi
Registration #7	2017-02-20	60.553 mi
Registration #8	2018-02-15	69.083 mi
Registration #9	2018-07-26	71.862 mi
Registration #10	2019-05-20	75.377 mi
Registration #11	2019-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2019-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2019-05-20	75.377 mi
Registration #16	2019-05-20	75.377 mi
Registration #17	2019-05-20	75.377 mi
Registration #18	2019-05-20	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1299 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	181935