



report date: 2024-03-29

General information

Make	KIA
Model	CEED CRDI VR7
Colour	Silver
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 2.750 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-15
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-05-10
<b>MOT pass rate</b>	89 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	6
<b>Total items failed</b>	3

<b>MOT #9</b>	2024-04-23 13:10
<b>MOT test number</b>	310127403041
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-05-10

<b>MOT #8</b>	2023-05-11 09:26
<b>MOT test number</b>	665708526333
<b>Result</b>	✓ Passed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Offside Rear Service brake binding but not excessively (1.2.1 (f))

<b>MOT #7</b>	2022-06-16 14:39
<b>MOT test number</b>	161095627117
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Offside Rear Service brake binding but not excessively (1.2.1 (f))

<b>MOT #6</b>	2021-06-23 14:41
<b>MOT test number</b>	634816589882
<b>Result</b>	✓ Passed

**MOT #5** 2020-08-03 15:40**MOT test number** 605005939696**Result** ✓ Passed**Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))**Advice** Offside Side repeater slightly discoloured (4.4.3 (a))**MOT #4** 2019-08-05 12:06**MOT test number** 137177585336**Result** ✓ Passed**MOT #3** 2018-08-13 15:24**MOT test number** 123618051562**Result** ✓ Passed**MOT #2** 2018-08-13 15:24**MOT test number** 381367299006**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Front Front fog lamp not working (4.5.1 (a) (ii))**MOT #1** 2017-08-15 14:08**MOT test number** 776624608028**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
10 May 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	10 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>SD14MUO</b>
Plate since	2024-03-29
Current registration	<b>SD14MUO</b>
Plate since	2024-03-29

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-04-26
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2014-04-26	19 mi
Registration #2	2017-08-15	31.545 mi
Registration #3	2018-08-13	48.214 mi
Registration #4	2018-08-13	48.214 mi
Registration #5	2019-08-05	64.389 mi
Registration #6	2020-08-03	73.753 mi
Registration #7	2020-08-03	73.753 mi
Registration #8	2020-08-03	73.753 mi
Registration #9	2020-08-03	73.753 mi
Registration #10	2020-08-03	73.753 mi
Registration #11	2020-08-03	73.753 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1489 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FCEZ116089