



LI3PCG

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 2


Date	2021-01-31
Pictures	4
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2024-06-07
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	7

MOT #16	2023-05-25 13:24
MOT test number	460563544528
Result	✓ Passed
Next expiry date	2024-06-07
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive Sills and arm mounts (5.3.6 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15	2022-05-25 10:54
MOT test number	534334083980
Result	✓ Passed
Advice	Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #14	2021-06-08 09:10
MOT test number	406484605771
Result	✓ Passed

MOT #13	2020-08-19 15:08
MOT test number	901146158126
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2020-08-17 10:29**MOT test number** 354320694033**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill holed (6.2.2 (d) (i))**Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #11** 2019-08-16 13:17**MOT test number** 773669403023**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2019-08-15 08:55**MOT test number** 168067648842**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MOT #9** 2018-08-22 11:03**MOT test number** 705924166769**Result** ✓ Passed**MOT #8** 2017-05-04 13:58**MOT test number** 158822997283**Result** ✓ Passed**Advice** Both front tyre walls damaged

**MOT #7** 2017-05-04 13:08**MOT test number** 702186688064**Result** ✗ Failed**Fail** Nearside Front Headlamp excessively deteriorated so that the light output is severely reduced main beam faulty (1.7.5a)**Advice** Both front tyre walls damaged**Fail** Headlamp not working on dipped beam both front dipp beams not working (1.7.5a)**MOT #6** 2016-03-14 13:10**MOT test number** 250183906501**Result** ✓ Passed**MOT #5** 2016-03-14 09:37**MOT test number** 766234224901**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2015-01-13 09:08**MOT test number** 756033815035**Result** ✓ Passed**MOT #3** 2014-09-17 12:35**MOT test number** 356130364496**Result** ✓ Passed



MOT #2	2012-11-22 13:49
MOT test number	588237822302
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Nail in offside rear tyre
Notice	Under-trays fitted obscuring some underside components
Notice	Oil leak

MOT #1	2011-11-28 10:25
MOT test number	828172731371
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
7 June 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-12-03
Last registration	2023-05-25
Complete history	See info



Registration #1	2008-12-03	21 mi
Registration #2	2011-11-28	16.410 mi
Registration #3	2012-11-22	22.060 mi
Registration #4	2014-09-17	35.897 mi
Registration #5	2015-01-13	37.232 mi
Registration #6	2016-03-14	44.811 mi
Registration #7	2016-03-14	44.813 mi
Registration #8	2017-05-04	50.622 mi
Registration #9	2017-05-04	50.622 mi
Registration #10	2018-08-22	54.527 mi
Registration #11	2019-05-25	55.557 mi
Registration #12	2019-05-25	55.557 mi
Registration #13	2019-05-25	55.557 mi
Registration #14	2019-05-25	55.557 mi
Registration #15	2019-05-25	55.557 mi
Registration #16	2019-05-25	55.557 mi
Registration #17	2019-05-25	55.557 mi
Registration #18	2019-05-25	55.557 mi
Registration #19	2019-05-25	55.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG