






report date: 2024-03-28

# General information

Make	FORD	
Model	TRANSIT 17 STR MINIBUS 100BHP	
Colour	White	
Year of manufacture	2006	
Gearbox	-MANUAL	

# Engine & fuel consumption

Power	100 BHP
Max. torque	285 Nm at 1.600 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	284 g/km
CO2 label	M



CarCheck.co.uk page 1/13



report date: 2024-03-28

# **MOT** history

MOT expiry date	2022-03-18
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	55
Total items failed	6

MOT #15		2021-03-19 14:58
MOT test	number	498045291381
Result		✓ Passed
Next expi	ry date	2022-03-18
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Advise vehicle tested with 16 seats	
Advice	Advise front pads low	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	)
Advice	Brake pedal travel quite long	
Advice	Offside Rear Seat belt webbing slightly damaged or frayed passanger (7.1.2 (b) (ii	))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Advise clutch and pedal rubbers slight wear	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (	=))
Advice	Advise offside marker light inoperative	

CarCheck.co.uk page 2/13



report date: 2024-03-28

**MOT #14** 2021-03-17 15:23

**MOT** test number 136299628138 Result × Failed Fail Fuel pipe damaged fuel tank breather hose (6.1.3 (c) (ii)) **Advice** Advise vehicle tested with 16 seats Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Advice Advise offside marker light inoperative Fail Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii)) Fail Offside Rear Brake pipe excessively damaged across axle (1.1.11 (c)) Advice Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i)) Advise clutch and pedal rubbers slight wear Advice

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice

**Advice** Advise front pads low

Fail Power steering pipe/hose modification unsafe insecure (2.1.5 (f) (i))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Rear Seat belt webbing slightly damaged or frayed passanger (7.1.2 (b) (ii))

Fail Nearside Rear All direction indicators incorrect colour (4.4.3 (a))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13		2020-02-14 10:28
MOT test	number	430582625322
Result		✓ Passed
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.1	L4 (a) (ii))
Advice	Central Prop shaft bearing has slight play (6.1.7 (b) (i))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #12		2019-01-11 14:54
MOT test	number	433270196630
Result		✓ Passed
Advice	Prop shaft bearing has slight play (6.1.7 (b) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))
Advice	12 passenger seats fitted at time of test	

MOT #11		2018-01-10 11:52
MOT test	number	402831765633
Result		✓ Passed
Advice	Direction indicators slightly discoloured both rear (1.4.A.2f)	
Advice	OSR axle seal slight leak	
Advice	Nearside Rear Outer Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	12 passenger seats fitted at time of test	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10

MOT test number

Result

Advice Brake pipe slightly corroded both front to rear (3.6.B.2c)

MOT #9

MOT test number

Result

Advice Nearside Front Outer Tyre worn close to the legal limit (4.1.E.2b)

Advice Brake pad(s) wearing thin both rear (3.5.1g)

MOT #8

MOT test number

447628905085

Result

Advice Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2014-01-08 11:38 **MOT** test number 886818004078 Result ✓ Passed Notice Play in steering rack inner joint(s) **Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)Advice Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)Advice Offside Rear Leaf spring has a slightly deteriorated anchor pin rubber bush not resulting in excessive movement (2.4.B.2) **Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Leaf spring has a slightly deteriorated anchor pin rubber bush not resulting in excessive movement (2.4.B.2)

CarCheck.co.uk page 5/13



MOT #6

**ND56EVX** 

report date: 2024-03-28

2013-01-07 10:48

MOT test number	736517703056
Result	<b>✓</b> Passed
MOT #5	2012-01-09 11:14
MOT test number	106819102495
Result	✓ Passed
MOT #4	2011-01-06 16:12

<b>MOT test</b>	number 336926601004	
Result	✓ Passed	
Advice	Nearside Rear Road wheel slightly damaged (4.2.A.1a)	
<b>Advice</b> (2.4.G.2)	Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement	

MOT #3		2010-01-04 13:46
MOT test	number	331714800016
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.D.1a)	
Advice	Rear brake disc slightly pitted (3.5.1g)	
Notice	Parking brake effciency just met	

MOT #2		2009-01-08 10:06
MOT test	number	673788609095
Result		<b>✓</b> Passed
Advice	Front brake disc slightly worn (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1e)	
Advice	Rear brake disc slightly worn (3.5.1g)	
Advice	Rear Brake pad(s) wearing thin (3.5.1e)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

**MOT #1** 2007-09-17 13:00

**MOT test number** 220360767210

**Result** ✓ Passed

CarCheck.co.uk page 7/13



ND56EVX report date: 2024-03-28

### Tax & MOT check

Tax expired: 1 March 2023



X MOT

Expired: 18 March 2022

Tax status	Expired at 1 March 2023
Days left	425 days too late
MOT expiry date	18 March 2022
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/13



report date: 2024-03-28

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

$\hat{}$	
Owner	history
OWITCE	ilistoi y

,		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	NK SIN	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-10-10
Last registration	2021-03-19
Complete history	See info



Registration #1	2006-10-10	24 mi
Registration #2	2007-09-17	11.471 mi
Registration #3	2009-01-08	16.065 mi
Registration #4	2010-01-04	22.040 mi
Registration #5	2011-01-06	27.524 mi
Registration #6	2012-01-09	32.841 mi
Registration #7	2013-01-07	38.642 mi
Registration #8	2014-01-08	42.105 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		71.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

# Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Additional information

Number of seats	17
Number of axles	2
Engine number	6P49079

CarCheck.co.uk page 13/13